Issue List

- RTU 1 - High Airflow
- RTU 1 - OA Filters Incorrectly Installed

05-20-24 CARMAX #7110 - DORAL, FL

Project Issue Information

Issue Name :	RTU 1 - High Airflow		
Description :	Current airflow measured at 17774CFM out of 10000CFM design (177%). Outside air filters were not installed in the RTU. Unable to adjust VFD, error messages given when any parameter was changed. Reducing the airflow via just the VFD also would prevent the unit from modulating speed, as only ~35Hz would be available. Sheave change recommended.		
Created By :	National TAB	**Assigned To :**	National TAB - Stephen Tassinaro
Status :	Open		
Priority :	High	**Asset Tag :**	
Originated Date :	05/22/2024 - Stephen Tassinaro - National TAB		

05-20-24 CARMAX #7110 - DORAL, FL

Project Issue Information

Issue Name : RTU 1 - OA Filters Incorrectly Installed

Description : The outside air filters were not correctly installed on RTU-1. All filters fell out of the unit and onto the rooftop when unit was tested in high speed.

Created By : National TAB

Assigned To : National TAB - Stephen Tassinaro

Status : Open

Priority : High

Asset Tag :

Originated Date : 05/22/2024 - Stephen Tassinaro - National TAB

Project Issue File Details

IMG_3058
05/22/2024

IMG_3057
05/22/2024