



Shake Shack (Oak Lawn, IL) - Commissioning

CheckList Information

Name :	FIV - (Above Ceiling) Electrical Rough-In	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Lighting & Power above ceiling inspection (main power - lighting symbol key attached)

- [Open](#) lighting_symbol_key.PNG

- Drive thru (space 111) inspected and compared to sheet E120. Yes

- [Open](#) FuseIT2021-07-02T1005298caf734a-c68b-407f-a1c4-abcdd97caaf5.jpg
- [Open](#) FuseIT2021-07-02T100602d244e082-1df2-45f7-a757-468048e10302.jpg
- [Open](#) drive_thru_lighting.PNG

- BOH kitchen prep (space 112) inspected and compared to sheet E120 Yes

- [Open](#) FuseIT2021-07-02T1007045140adb2-82af-46bb-a73d-0911633a84df.jpg
- [Open](#) boh_serve_line_lighting.PNG

- BOH kitchen cook and serve lines areas inspected (space 109 & 110) and compared to sheet E120 Yes

- [Open](#) FuseIT2021-07-02T10080323d1dd76-499c-4fb9-b9f9-336c1a9e63ee.jpg
- [Open](#) cookline_and_serve_line_lighting.PNG

- Office (space 115) inspected and compared to sheet E120 Yes

- [Open](#) managers_office.PNG
- [Open](#) FuseIT2021-07-02T101240425aa047-f818-4c3f-a3f7-4d6acc9a838f.jpg

- Mechanical room (space 116) lighting compared to sheet E120 Yes

- [Open](#) mech_room.PNG
- [Open](#) FuseIT2021-07-02T101329167525f0-e465-43a4-a948-e7c93d00b13e.jpg

- Mens and Womens Restrooms (space 106 and 107) lighting compared to sheet E120 Yes

- [Open](#) restrooms.PNG
- [Open](#) FuseIT2021-07-02T10090186c00d85-45c0-4da3-a351-bb8871057af2.jpg
- [Open](#) FuseIT2021-07-02T100917013f6f29-70ee-4fa5-9dc7-25724fe9f6d1.jpg

- Dining room soffit details compared to sheet E120 Yes

- [Open](#) soffit_lighting_power.PNG

- Main Dining Room compared to sheet E120 Yes

- [Open](#) dining_room.PNG
- [Open](#) FuseIT2021-07-02T1010275a0abdda-89c5-4099-a4ea-c570bb1b6469.jpg
- [Open](#) e_euh_vestibule.PNG

- Patio Lighting & Power Junctions compared to sheet E120 Yes

- [Open](#) FuseIT2021-07-02T101140eb96304e-58f5-47df-a020-fc11c6a35e7c.jpg
- [Open](#) FuseIT2021-07-02T101151b408a0d6-d77f-4027-b657-6d87f78f3fc7.jpg
- [Open](#) epatio.PNG
- [Open](#) epation_heater_above_celing.PNG