

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: Deficiency Report**  
**Function: Test, Adjust, & Balance**  
**Date: 05/06/2025**  
**Completed By: National TAB**

# PROJECT

**05-05-25 WHATABURGER #1365 DAPHNE, AL**

US HIGHWAY 98 & LAVENDER LANE

DAPHNE, AL 36526

**Client**

Whataburger Restaurants  
300 Concord Plaza Dr  
San Antonio, TX 78216

## Issue List

- EF-1 - Not Powered
- RTU 1 - Float Switch



**05-05-25 WHATABURGER #1365 DAPHNE, AL**

**Project Issue Information**

**Issue Name :** EF-1 - Not Powered  
**Description :** EF-1 (restrooms) is currently not powered. Speed control potentiometer is missing. Recommend installing.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :** EF1  
**Originated Date :** 05/06/2025 - Mark Johnson - National TAB

Project Issue File Details





**05-05-25 WHATABURGER #1365 DAPHNE, AL**

**Project Issue Information**

**Issue Name :** RTU 1 - Float Switch  
**Description :** RTU 1 (kitchen) periodically locks out due to float switch activation. Excessive condensate is present inside unit, and drains slowly. Recommend inspection.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :** RTU1  
**Originated Date :** 05/06/2025 - Mark Johnson - National TAB

Project Issue File Details



05/06/2025



05/06/2025



05/06/2025