

PlanGrid Task Report - Dec 16, 2024

Prepared by Dale Wheeler

Dec 16, 2024

Description

3 tasks in this report.

Contents

#13 [SITE 500] [NEW] TAB is complete.	2
#12 [UNIT 999] [NEW] (MISC) [[RETAINING TIES ON WIRES].....	3
#11 [UNIT 999] [NEW] (MISC) [UNIT DISCONNECT]	5

L05381_RELO Monroe (NC) FSU

2579 West Roosevelt Boulevard, Monroe, North Carolina

L2220005381

#13 [SITE 500] [NEW] TAB is complete.

Status

Open

Start Date

Dec 12, 2024

Type

Planned Work

Created

Dec 16, 2024 3:43 PM
dale@nationaltab.com

Description

TAB is complete with only
non-critical tasks open

Last Updated

Dec 16, 2024 3:44 PM

#12 [UNIT 999] [NEW] (MISC) [[RETAINING TIES ON WIRES]

Status

Open

Start Date

Dec 11, 2024

Type

Planned Work

Created

Dec 16, 2024 3:34 PM
dale@nationaltab.com

Description

AC1, AC2, AC3 wires are missing factory retaining ties. This is a Lennox factory issue.

Last Updated

Dec 16, 2024 3:42 PM

Photos



IMG_6432
Dale Wheeler
Dec 16, 2024 3:34 PM



IMG_6430
Dale Wheeler
Dec 16, 2024 3:34 PM

L05381_RELO Monroe (NC) FSU

2579 West Roosevelt Boulevard, Monroe, North Carolina

L2220005381



IMG_6431

Dale Wheeler

Dec 16, 2024 3:34 PM

L05381_RELO Monroe (NC) FSU

2579 West Roosevelt Boulevard, Monroe, North Carolina

L2220005381

#11 [UNIT 999] [NEW] (MISC) [UNIT DISCONNECT]

Status

Open

Start Date

Dec 18, 2024

Type

Planned Work

Created

Dec 16, 2024 3:33 PM
dale@nationaltab.com

Description

AC2 unit disconnect panel is incorrect. The correct style disconnect / access panel has been shipped from Lennox per mechanical.

Last Updated

Dec 16, 2024 3:38 PM

Photos



IMG_6501

Dale Wheeler

Dec 16, 2024 3:34 PM