

# PlanGrid Task Report - Feb 14, 2024

Prepared by Will T

Feb 14, 2024

## Description

6 tasks in this report.

## Contents

#123 [CNTL 098] Ansul pull labeling. ....	2
#122 [CNTL 107] (MISC) Missing Ansul pull stations.....	4
#121 [CNTL 107] (MISC) Zone Damper Thermostats do not have power .....	6
#120 [EXHA 127] Grease exhaust duct is not supported.....	8
#119 [UNIT 152] Trane equipment missing field kits. ....	10
#118 [UNIT 168] Equipment not secured properly. ....	12

## #123 [CNTL 098] Ansul pull labeling.

### Status

Open

### Start Date

Feb 6, 2024

### Sheet

M-301

### Type

Planned Work

### Created

Feb 6, 2024 3:16 PM  
ianf@nationaltab.com

### List

4.9 Mechanical Test &  
Balance


### Last Updated

Feb 9, 2024 8:53 AM

### Description

Label all Ansul pull stations  
for which hoods they serve.

### Photos



L04916\_Princeton Woods FSU (Dumfries, VA)

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200



Missing Ansul Label

**Ian Fuller**

Feb 6, 2024 3:32 PM

---

## #122 [CNTL 107] (MISC) Missing Ansul pull stations

**Status**

Open

**Start Date**

Feb 6, 2024

**Sheet**

M-301

**Type**

Planned Work

**Created**


Feb 6, 2024 3:16 PM  
ianf@nationaltab.com

**List**

4.9 Mechanical Test &  
Balance

**Last Updated**

Feb 9, 2024 8:53 AM



**Description**

Ansul pull stations are not yet installed at locations designated

**Photos**



Missing Ansul 1

**Ian Fuller**

Feb 6, 2024 3:32 PM



Missing Ansul 2

**Ian Fuller**

Feb 6, 2024 3:32 PM

# #121 [CNTL 107] (MISC) Zone Damper Thermostats do not have power

Status  
Closed

Start Date  
Feb 6, 2024

Sheet  
M-201

Type  
Planned Work

Created  
Feb 6, 2024 3:16 PM  
ianf@nationaltab.com


List  
4.9 Mechanical Test & Balance

Last Updated  
Feb 9, 2024 8:53 AM

Description  
Thermostat controlling zone dampers need transformer installed in order to power thermostats

Closed At  
Feb 7, 2024

Photos





IMG\_6512

Ian Fuller

Feb 6, 2024 3:33 PM

# #120 [EXHA 127] Grease exhaust duct is not supported.

**Status**  
Open

**Start Date**  
Feb 6, 2024

**Sheet**  
M-401

**Type**  
Planned Work

**Created**  
Feb 6, 2024 3:16 PM  
ianf@nationaltab.com


**List**  
4.9 Mechanical Test &  
Balance

**Last Updated**  
Feb 9, 2024 8:53 AM

## Description

Exhaust duct for EF#1 is to be supported per kitchen hood exhaust fan detail on 6'0" centers.

## Photos





Duct Support Spacing

**Ian Fuller**

Feb 6, 2024 3:33 PM



Grease Duct Supports

**Ian Fuller**

Feb 6, 2024 3:33 PM

## #119 [UNIT 152] Trane equipment missing field kits.

**Status**

Closed

**Start Date**

Feb 6, 2024

**Sheet**

M-501

**Type**

Planned Work

**Created**

Feb 6, 2024 3:16 PM  
ianf@nationaltab.com

**List**

4.9 Mechanical Test &  
Balance

**Last Updated**


Feb 9, 2024 8:53 AM

**Description**

Trane equipment does not have additional manufacturer supplied, field installed relays, delay timer, or discharge temperature controller with FAT scheduled in design.

**Closed At**

Feb 8, 2024



**Photos**



Missing Relay

Ian Fuller

Feb 6, 2024 3:36 PM



Missing Delay Timer and Temperature Controller

Ian Fuller

Feb 6, 2024 3:36 PM

# #118 [UNIT 168] Equipment not secured properly.

## Status

Open

## Start Date

Feb 6, 2024

## Sheet

M-250

## Type

Planned Work

## Created

Feb 6, 2024 3:16 PM  
ianf@nationaltab.com

## List

4.9 Mechanical Test &  
Balance


## Last Updated

Feb 9, 2024 8:56 AM

## Description

Equipment not secured properly to curb, high wind/ seismic clips not installed. Mechanical stated that unit package did not come with seismic clips.

## Photos



L04916\_Princeton Woods FSU (Dumfries, VA)

3350 Pine Bluff Drive, Dumfries, Virginia

L049160200



Missing Seismic Clips

**Ian Fuller**

Feb 6, 2024 3:36 PM