

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Punch List
Function: Test, Adjust, & Balance
Date: 12/09/2025
Completed By: National TAB

PROJECT
12-08-25 FREDDYS MIDDLETOWN, DE

645 South Ridge Avenue

MIDDLETOWN , DE 19709

Client

JRI Hospitality Management
621 Westport Blvd
Salina, KS 67401

National TAB

Project: 12-08-25 FREDDYS MIDDLETOWN, DE

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- RTU 1 low flow




12-08-25 FREDDYS MIDDLETOWN, DE

Project Issue Information

Issue Name : RTU 1 low flow
Description : RTU 1 supply drop has a 4" opening and is not properly attached to discharge. Unit is losing air inside the ceiling.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :** RTU1
Originated Date : 12/09/2025 - Jearod Ferrette - National TAB

Project Issue File Details



12/09/2025



12/09/2025



12/09/2025