

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: PUNCH
Function: Test, Adjust, & Balance
Date: 02/10/2026
Completed By: National TAB

PROJECT
02-09-26 QT #1098 ROCK HILL, SC

664 ANDERSON RD NORTH

ROCK HILL, SC

Client

QUIKTRIP
4705 SOUTH 129TH EAST AVENUE
TULSA, OK 74134

National TAB

Project: 02-09-26 QT #1098 ROCK HILL, SC

Table Of Contents

Section	Page #
Remarks	3

Issue List

- EF-1: High total exhaust
- RTU2: Economizer not functional
- RTU3: Incorrect cookline diffusers



02-09-26 QT #1098 ROCK HILL, SC

Project Issue Information

Issue Name : EF-1: High total exhaust
Description : Potentiometer set to lowest speed on speed dial. No low speed potentiometer present, cannot lower fan speed. ~200% of design.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 02/10/2026 - Cody Mauro - National TAB

Project Issue File Details



02/10/2026



02/10/2026



02-09-26 QT #1098 ROCK HILL, SC

Project Issue Information

Issue Name : RTU2: Economizer not functional
Description : RTU3 economizer not functional, does not communicate when setting adjusting setpoints in emerson controls. Unable to manually loosen actuator screws for manually OA adjustment.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :**
Originated Date : 02/10/2026 - Cody Mauro - National TAB

Project Issue File Details



02/10/2026



02/10/2026



02/10/2026



02-09-26 QT #1098 ROCK HILL, SC

Project Issue Information

Issue Name : RTU3: Incorrect cookline diffusers
Description : Cookline diffusers are supposed to be TITUS 300FS with their proper deflection blades.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :**
Originated Date : 02/09/2026 - Cody Mauro - National TAB

Project Issue File Details



02/09/2026



02/09/2026