

Report By:

**National TAB
105 Stone Village Drive
Fort Mill, SC 29708**



**Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 12/17/2025
Completed By: National TAB**

PROJECT
City BBQ (Johnson City, TN)

421 State of Franklin Rd.

Johnson City, TN 37604

Client

F.G. Schaefer Co.
2145 Florence Ave
PO Box 6505
Cincinnati, OH 45206

Issue List

- Missing grease cups
- No OA on RTU's
- Only PSP on Hood 2



City BBQ (Johnson City, TN)

Project Issue Information

Issue Name : Missing grease cups
Description : The KEF for Hood 2, as well as all three exhaust fans for the smokers are missing their grease capture cups on the outside of the fans.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Medium **Asset Tag :** KH-1
Originated Date : 12/17/2025 - Christian Moller - National TAB

Project Issue File Details



12/17/2025



12/17/2025



City BBQ (Johnson City, TN)

Project Issue Information

Issue Name : No OA on RTU's
Description : None of the RTU's have OA intakes. OA could not be balanced.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/17/2025 - Christian Moller - National TAB

Project Issue File Details



12/17/2025



12/17/2025



12/17/2025



City BBQ (Johnson City, TN)


Project Issue Information

Issue Name : Only PSP on Hood 2
Description : The plans show an ACPSP on hood 2, with supply running from RTU 2 to the hood. There is only the PSP portion on the hood, no supply from the RTU.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :** KH-1
Originated Date : 12/17/2025 - Christian Moller - National TAB

Project Issue File Details



12/17/2025



12/17/2025