

# 5571 PRE-GRID PUNCH LIST

Prepared by Ben Searles

Mar 21, 2025

## Description

4 tasks in this report.

## Contents

#35 [HOOD 509] [NEW] Hood back panes. ....	2
#34 [UNIT 505] [NEW] Equipment wiring portals. ....	3
#33 [UNIT 506] [NEW] Equipment GFI outlets. ....	4
#32 [UNIT 510] [NEW] Gas inlet grommet. ....	5

**#35 [HOOD 509] [NEW] Hood back panes.**

**Status**

Open

**Start Date**

Mar 20, 2025

**Type**

Planned Work

**Created**

Mar 21, 2025 11:24 AM  
bens@nationaltab.com

**Description**

Hoods are to be secured to back panes via pre-punch holes with stainless steel screws.

**Last Updated**

Mar 21, 2025 11:25 AM

**Photos**



IMG\_0606

Ben Searles

Mar 21, 2025 11:25 AM

### #34 [UNIT 505] [NEW] Equipment wiring portals.

<b>Status</b> Open	<b>Start Date</b> Mar 20, 2025
<b>Type</b> Planned Work	<b>Created</b> Mar 21, 2025 11:24 AM bens@nationaltab.com
<b>Description</b> AC1 is missing a low voltage wiring grommet.	<b>Last Updated</b> Mar 21, 2025 11:25 AM

#### Photos



IMG\_0609

Ben Searles

Mar 21, 2025 11:25 AM

### #33 [UNIT 506] [NEW] Equipment GFI outlets.

**Status**

Open

**Start Date**

Mar 20, 2025

**Type**

Planned Work

**Created**

Mar 21, 2025 11:24 AM  
bens@nationaltab.com

**Description**

AC4 GFI outlet is not installed.

**Last Updated**

Mar 21, 2025 11:26 AM

**Photos**



IMG\_0616

Ben Searles

Mar 21, 2025 11:26 AM

### #32 [UNIT 510] [NEW] Gas inlet grommet.

**Status**

Open

**Start Date**

Mar 20, 2025

**Type**

Planned Work

**Created**

Mar 21, 2025 11:24 AM  
bens@nationaltab.com

**Description**

AC1 gas inlet grommet is missing at the gas line/RTU penetration point.

**Last Updated**

Mar 21, 2025 11:26 AM

**Photos**



IMG\_0608

Ben Searles

Mar 21, 2025 11:26 AM