

5571 TAB PUNCH LIST

Prepared by Ben Searles

May 8, 2025

Description

9 tasks in this report.

Contents

#177 [CNTL 508] [NEW] Controls labeling.....	2
#176 [CNTL 509] [NEW] Ansul pull labeling.....	3
#175 [CURT 501] [NEW] Air curtain power.	4
#174 [UNIT 999] [NEW] AC filters	5
#173 [UNIT 506] [NEW] Equipment GFI outlets.....	6
#172 [REFG 500] [NEW] WIC/WIF temperatures.	7
#171 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.....	8
#170 [REFG 516] [NEW] Condenser electrical disconnects.	9
#169 [REFG 999] [NEW] WIF alarm.	10

#177 [CNTL 508] [NEW] Controls labeling.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

Label all smoke
annunciators for which piece
of equipment they serve.

Last Updated

May 8, 2025 2:42 PM

Photos



IMG_1030

Ben Searles

May 8, 2025 2:42 PM

#176 [CNTL 509] [NEW] Ansul pull labeling.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

Label ansul pull station 1 for which hood it serves. The other two pull stations are labeled properly.

Last Updated

May 8, 2025 2:42 PM

Photos



IMG_1031

Ben Searles

May 8, 2025 2:42 PM

#175 [CURT 501] [NEW] Air curtain power.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

Air door 2 power does not appear to be wired at time of TAB inspection.

Last Updated

May 8, 2025 2:42 PM

Photos



IMG_1043

Ben Searles

May 8, 2025 2:42 PM

#174 [UNIT 999] [NEW] AC filters

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

Mechanical should provide
an extra set of filters for each
of the units.

Last Updated

May 8, 2025 2:40 PM

#173 [UNIT 506] [NEW] Equipment GFI outlets.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com


Description

AC4 GFI outlet missing. All other units have GFI's installed and powered.

Last Updated

May 8, 2025 2:42 PM

Photos



IMG_1032

Ben Searles

May 8, 2025 2:42 PM

#172 [REFG 500] [NEW] WIC/WIF temperatures.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

WIF boxe is not holding specified temperature. At the time of inspection, the WIF was holding at around 20 degrees.

Last Updated

May 8, 2025 2:42 PM

Photos



IMG_1036

Ben Searles

May 8, 2025 2:42 PM

#171 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

PVC pipe chase risers are sealed with spray foam, but are not cut flush with a layer of silicone over the top.

Last Updated

May 8, 2025 2:43 PM

Photos



IMG_1046

Ben Searles

May 8, 2025 2:43 PM

#170 [REFG 516] [NEW] Condenser electrical disconnects.

Status

Open

Start Date

May 8, 2025

Type

Planned Work

Created

May 8, 2025 2:40 PM
bens@nationaltab.com

Description

Electrical disconnects are not properly labeled.

Last Updated

May 8, 2025 2:43 PM

Photos



IMG_1034

Ben Searles

May 8, 2025 2:43 PM

#169 [REFG 999] [NEW] WIF alarm.

Status Open	Start Date May 8, 2025
Type Planned Work	Created May 8, 2025 2:40 PM bens@nationaltab.com
Description The WIF is experiencing an active alarm.	Last Updated May 8, 2025 2:43 PM

Photos



IMG_1035
Ben Searles
May 8, 2025 2:43 PM