



Warabeya North America (Columbus, OH)

Project Issue Information

Issue Name : AHU1-Return-RE36 duct Issue
Description : No motorized Damper installed in Duct going to RE36 Relief fan. When Fan is off per SOO AHU is pulling air in not only from returns from space but also pulling air in from outside through re36 relief duct causing inadequate return airflow & too much OA for AHU Unit.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : High **Asset Tag :**
Originated Date : 09/21/2025 - Joe Hertenstein - National TAB

Project Issue File Details

