



Nestle (Mt Sterling, KY)

CheckList Information

Name :	EF-58 / REAR OFFICE RESTROOMS	Status :	NotSubmitted
Assigned Organization :	National TAB	Asset :	
Requesting Organization :	National TAB		

CheckList Item Details

Observe Unit to ensure operational and no visual issues. If any observed, comment. Note # of duct drops.	Dd, no speed control. Unit is too big for the curb. But there is no leakage
Attach picture of asset.	Yes
<ul style="list-style-type: none"> • Open File.jpg 	
Fan total pressure recorded.	Yes
Is Fan interlocked with any other asset? if so, list:	No
When is fan used (application) and any specific time?	Restroom?
UNIT DATA:	GREENHECK, MN: G-101-A, SN:04128285 MOTOR: 0.25H, 1725, PH1, 115V, 3.4A CFM:726 SP:-1.08"