

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: Deficiency\_Report**  
**Function: Test, Adjust, & Balance**  
**Date: 07/22/2024**  
**Completed By: National TAB**

**PROJECT**  
**07-22-24 WAWA #5422 OCALA, FL**

2277 SW Hwy 484

OCALA, FL

**Client**

Wawa  
260 West Baltimore Pike  
Wawa, PA 19063

# National TAB

Project: 07-22-24 WAWA #5422 OCALA, FL

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- EF-1
- EF-1 GRAVITY DAMPER
- RESTROOM EXHAUST DAMPERS
- RTU-1 OA FILTER
- RTU-2 OA FILTER



**07-22-24 WAWA #5422 OCALA, FL**


**Project Issue Information**

**Issue Name :** EF-1  
**Description :** EXHAUST FAN 1 HAS NOT BEEN WIRED. THERE IS NO POWER TO MOTOR AND POWER DISCONNECT HAS NOT BEEN ASSEMBLED.  
**Created By :** National TAB                      **Assigned To :** National TAB - Will Turnbough  
**Status :** Closed  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 07/22/2024 - Kristopher Passley - National TAB

Project Issue File Details



07/22/2024



07/22/2024

Project Issue Response Details

- **07/24/2024 National TAB - Kristopher Passley**
  - EF-1 POWER HAS BEEN CONNECTED.



**07-22-24 WAWA #5422 OCALA, FL**

**Project Issue Information**

**Issue Name :** EF-1 GRAVITY DAMPER  
**Description :** GRAVITY DAMPER FOR EXHAUST FAN 1 IS NOT INSTALLED. RECOMMEND MECHANICAL TO INSTALL ONE PER PLAN DESIGN.  
**Created By :** National TAB                      **Assigned To :** National TAB - Will Turnbough  
**Status :** Closed  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/22/2024 - Kristopher Passley - National TAB

Project Issue File Details



Project Issue Response Details

- **10/22/2024 National TAB - Kristopher Passley**
  - ISSUES IS RESOLVED. GRAVITY DAMPPER HAS BEEN INSTALLED







**07-22-24 WAWA #5422 OCALA, FL**

**Project Issue Information**

**Issue Name :** RESTROOM EXHAUST DAMPERS  
**Description :** DAMPERS FOR THE RESTROOM EXHAUST VENTS, EF1-5,EF1-6,EF1-7 (SEE GRD LAYOUT), ARE IN AN AREA THAT IS INACCESSIBLE ABOVE HARD CEILING. NEED DAMPERS TO BE ACCESSIBLE IN ORDER TO BRING EXHAUST AIRFLOW INTO DESIGN.  
**Created By :** National TAB                      **Assigned To :** National TAB - Will Turnbough  
**Status :** Closed  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 07/24/2024 - Kristopher Passley - National TAB

Project Issue File Details



07/24/2024



07/24/2024

07-22-24 WAWA #5422 OCALA, FL

**Project Issue Information**

**Issue Name :** RTU-1 OA FILTER  
**Description :** OUTSIDE AIR FILTER HAS NOT BEEN INSTALLED ON RTU-1.  
**Created By :** National TAB                      **Assigned To :** National TAB - Will Turnbough  
**Status :** Closed  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/22/2024 - Kristopher Passley - National TAB

Project Issue File Details



07/22/2024

Project Issue Response Details

- **10/22/2024 National TAB - Kristopher Passley**
  - ISSUES IS RESOLVED. OA FILTERS HAS BEEN INSTALLED.



10/22/2024





**07-22-24 WAWA #5422 OCALA, FL**

**Project Issue Information**

**Issue Name :** RTU-2 OA FILTER  
**Description :** RTU-2 OUTSIDER AIR FILTER IS NOT INSTALLED.  
**Created By :** National TAB                      **Assigned To :** National TAB - Will Turnbough  
**Status :** Closed  
**Priority :** Medium                                      **Asset Tag :**  
**Originated Date :** 07/22/2024 - Kristopher Passley - National TAB

Project Issue File Details



Project Issue Response Details

- **10/22/2024 National TAB - Kristopher Passley**
  - ISSUES IS RESOLVED. OA FILTERS HAS BEEN INSTALLED.



