

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246

NATIONAL

TAB

Comfort. Under control.

Report: ISSUE REPORT
Function: Test, Adjust, & Balance
Date: 6/30/2022

PROJECT
06-27 CULVERS - EASTLAKE, OH

34820 VINE ST

EASTLAKE, OH

Client

Accurex

PO Box 410

Schofield, WI 54476

National TAB

Project: 06-27 CULVERS - EASTLAKE, OH

Table Of Contents

Section	Page #
Issue Data	3



Comfort. Under control.

06-27 CULVERS - EASTLAKE, OH

Project Issue Information

Issue Name : Diffuser 2-16 duct connection is extremely leaky
Description : Diffuser and duct is not sealed
Created By : National TAB **Assigned To :** National TAB - Tyler Youells
Status : Open
Originated Date : 06/29/2022 - Tyler Youells - National TAB

Project Issue File Details



FuseITd30ff2c393ba4fbe9c00ca08e5a9cc9e.jpeg



FuseITb6c57f6c0e0f4c919679d2f68c223cb2.jpeg



Comfort. Under control.

06-27 CULVERS - EASTLAKE, OH

Project Issue Information

Issue Name : Diffuser 2-9 Takeoff

Description : Takeoff was not secured falls right off the duct causing leakage

Created By : National TAB

Assigned To : National TAB - Tyler Youells

Status : Open

Originated Date : 06/30/2022 - Tyler Youells - National TAB

Project Issue File Details



FuseIT758c48ddd34c4e5db0323
42e70a044f4.jpeg



Comfort. Under control.

06-27 CULVERS - EASTLAKE, OH

Project Issue Information

Issue Name : Grease cups not installed

Description : Hood exhaust fans do not have grease cups installed

Created By : National TAB

Assigned To : National TAB - Tyler Youells

Status : Open

Originated Date : 06/30/2022 - Tyler Youells - National TAB

Project Issue File Details



FuselTa81274ff92534f8f958bedc
38ddc6fb3.jpeg



Comfort. Under control.

06-27 CULVERS - EASTLAKE, OH

Project Issue Information

Issue Name : Various Diffuser Issues that need remedy

Description : Kitchen rtu diffuser issues 2-3 missing damper also damper stuck open 2-4 missing damper handle 2-5 damper stuck 2-7 damper handle strapped over with panduit 2-9 takeoff completely disconnected from supply trunk 2-10 no damper flex at a tight angle 2-11 flex duct kink 2-12 damper stuck flex kink 2-14 no access to damper 2-15/2-16 need to be boxes need to be sealed. RTU - 1 Diffuser 1-2 did not have a damper 1-3 and 1-25 no accessible damper 1-6 flex duct kink 1-9 1-10 and 1-12 no damper installed 1-13 no damper 1-14 no damper 1-20 no damper / or doesn't work 1-23 and 1-24 damper stuck closed

Created By : National TAB

Assigned To : National TAB - Tyler Youells

Status : Open

Originated Date : 06/30/2022 - Tyler Youells - National TAB