

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 04/03/2026
Completed By: National TAB

PROJECT

03-30-26 Freddys - East Dothan, AL

3265 & 3269 ROSS CLARK CIRCLE

DOTHAN, AL 36303

Client

WinCo LLC

Issue List

- EF 1 Not Powered
- RTU 1 - Missing Dampers



03-30-26 Freddys - East Dothan, AL

Project Issue Information

Issue Name : EF 1 Not Powered
Description : EF 1 (men’s restroom) is not powered, and does not switch on with the restroom lights. Recommend electrical inspection.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : High **Asset Tag :**
Originated Date : 04/03/2026 - Mark Johnson - National TAB

Project Issue File Details





03-30-26 Freddys - East Dothan, AL

Project Issue Information

Issue Name : RTU 1 - Missing Dampers
Description : Supply diffusers in the restrooms and hallway are missing face-accessible dampers for balancing. Duct runs are located above hard ceiling and not accessible.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 04/03/2026 - Mark Johnson - National TAB

Project Issue File Details



04/03/2026



04/03/2026



04/03/2026