

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: Punchlist**  
**Function: Test, Adjust, & Balance**  
**Date: 11/26/2025**  
**Completed By: National TAB**

# PROJECT

## 11-24-25 CHIPOTLE #5571 MIDDLEBURG, FL

1694 BLANDING BLVD

MIDDLEBURG, FL 32068

### Client

Chipotle Mexican Grill  
610 Newport Center Drive, Suite 1100  
Newport Beach, CA 92660

# National TAB

Project: 11-24-25 CHIPOTLE #5571 MIDDLEBURG, FL

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- Diffuser noise
- MAU leak above hood
- RTU2 Economizer



**11-24-25 CHIPOTLE #5571 MIDDLEBURG, FL**

**Project Issue Information**

**Issue Name :** Diffuser noise  
**Description :** Diffusers 8 9 and 10 (the office and dishwashing areas) create noise. Possibly due to 4 way deflectors. Not at a level likely to be noticeable or bothersome during store operation. No further action recommended at this time.


**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein

**Status :** Open

**Priority :** InfoOnly                                      **Asset Tag :** RTU 1

**Originated Date :** 11/26/2025 - Jackson Gunnels - National TAB

Project Issue File Details





**11-24-25 CHIPOTLE #5571 MIDDLEBURG, FL**


**Project Issue Information**

**Issue Name :** MAU leak above hood  
**Description :** There is a moderate air leak where the middle PSP riser joins to the hood.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 11/26/2025 - Jackson Gunnels - National TAB


Project Issue File Details



11/26/2025



11/26/2025



11/26/2025



**11-24-25 CHIPOTLE #5571 MIDDLEBURG, FL**

**Project Issue Information**

**Issue Name :** RTU2 Economizer  
**Description :** Unit 2 ECONOMIZER does not respond to commands. Returns value of -1.3. Inspected actuator connector, wiring is correct.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :** RTU2  
**Originated Date :** 11/26/2025 - Jackson Gunnels - National TAB

Project Issue File Details

