



Comfort. Under control.

09-26 HAWAIIAN BROS - EDWARDSVILLE, MO

Project Issue Information

Issue Name : EF1-4 Grease Cup
Description : Grease cups are not installed for hood exhaust fans.
Created By : National TAB **Assigned To :** National TAB - Travis Halter
Status : Open
Originated Date : 09/26/2022 - Travis Halter - National TAB

Project Issue File Details



FuseIT3d737ebc6d0840....



FuseIT55a8780abc9344....



Comfort. Under control.

09-26 HAWAIIAN BROS - EDWARDSVILLE, MO

Project Issue Information

Issue Name : HD1&2 Control Valve

Description : Valve is not installed

Created By : National TAB

Assigned To : National TAB - Travis Halter

Status : Open

Originated Date : 09/26/2022 - Travis Halter - National TAB

Project Issue File Details



FuselT9f13b906869f45....

Project Issue Response Details

- **09/27/2022 National TAB - Travis Halter**
 - Control valve installed, still needs to be wired back to control panel.



FuselT82195afe7d014d.jpeg

- **09/27/2022** **National TAB - Travis Halter**

- Gas lines are still being connected, unable to turn on kitchen equipment for final smoke test.
-



Comfort. Under control.

09-26 HAWAIIAN BROS - EDWARDSVILLE, MO

Project Issue Information

Issue Name : HD1&2 Lights

Description : The lights under the hood do not come on

Created By : National TAB

Assigned To : National TAB - Travis Halter

Status : Open

Originated Date : 09/27/2022 - Travis Halter - National TAB

Project Issue File Details



FuseIT8724325403b142....



FuseIT57ef0cd6b9bd48....



Comfort. Under control.

09-26 HAWAIIAN BROS - EDWARDSVILLE, MO

Project Issue Information

Issue Name : Hood Error

Description : "Core #01 fault pressure switch fault" on hoods. This keeps the DOAD units off until resolved.

Created By : National TAB

Assigned To : National TAB - Travis Halter

Status : Open

Originated Date : 09/27/2022 - Travis Halter - National TAB

Project Issue File Details



FuselT059d3ae38a4c47....

Project Issue Response Details

- **09/27/2022 National TAB - Travis Halter**
 - TAB was able to be finished with this fault active.