

# PlanGrid Task Report - May 6, 2025

Prepared by Stephen Tassinaro

May 6, 2025

## Description

2 tasks in this report.

## Contents

#7 [CURT 501] [NEW] Air curtain power. ....	2
#6 [EXHA 507] [NEW] Exhaust fan drain line.....	5

**L05401\_West Sanford FSU (FL)**

High Water Lane, Florida

L1020005401

**#7 [CURT 501] [NEW] Air curtain power.**

**Status**

Open

**Start Date**

Nov 11, 2024

**Type**

Planned Work

**Created**

Nov 12, 2024 10:45 AM  
ianf@nationaltab.com

**Description**

Air curtain #2 power does not cycle properly from local disconnect at time of TAB inspection.

**Last Updated**

May 6, 2025 11:03 AM

**Comments**

Found to be not operational. Video uploaded.

Stephen Tassinaro May 6, 2025

**Photos**

**L05401\_West Sanford FSU (FL)**

High Water Lane, Florida

L1020005401



IMG\_6078

**Stephen Tassinaro**

May 6, 2025 11:02 AM

[Download video](#)



IMG\_6077

**Stephen Tassinaro**

May 6, 2025 11:02 AM

**L05401\_West Sanford FSU (FL)**

High Water Lane, Florida

L1020005401



IMG\_8898

**Ian Fuller**

Nov 12, 2024 10:54 AM

**L05401\_West Sanford FSU (FL)**

High Water Lane, Florida

L1020005401

**#6 [EXHA 507] [NEW] Exhaust fan drain line.**

**Status**

Open

**Start Date**

Nov 11, 2024

**Type**

Planned Work

**Created**

Nov 12, 2024 10:45 AM  
ianf@nationaltab.com

**Description**

Exhaust fan drain is not properly installed. Drain need to be glued together.

**Last Updated**

May 6, 2025 11:08 AM

**Comments**

Drains found to not be glued.

Stephen Tassinaro May 6, 2025

**Photos**

**L05401\_West Sanford FSU (FL)**

High Water Lane, Florida

L1020005401



IMG\_6083

**Stephen Tassinaro**

May 6, 2025 11:08 AM



IMG\_8902

**Ian Fuller**

Nov 12, 2024 10:53 AM