

Report By:

National TAB



Report: Deficiency Report

Function: Test, Adjust, & Balance

Date: 12/08/2025

Completed By: National TAB

PROJECT

11-24-25 WHATABURGER #1667 LARGO, FL

10150 ULMRETON ROAD

LARGO, FL 33771

Client

Whataburger Restaurants

300 Concord Plaza Dr

San Antonio, TX 78216

Issue List

- Dining Room - Broken Dampers
- Economizers Not Operational



11-24-25 WHATABURGER #1667 LARGO, FL

Project Issue Information

Issue Name : Dining Room - Broken Dampers
Description : Several dampers in the dining room broke when attempting to adjust. Existing damper handles are brittle and prone to failure. Recommend mechanical inspection. Unable to balance the dining room until broken dampers are repaired.

Created By : National TAB **Assigned To :** National TAB - Will Turnbough

Status : Open


Priority : Urgent **Asset Tag :**

Originated Date : 12/08/2025 - Mark Johnson - National TAB

Project Issue File Details



12/08/2025



12/08/2025




11-24-25 WHATABURGER #1667 LARGO, FL

Project Issue Information

Issue Name : Economizers Not Operational
Description : All RTU economizers are not functional. For RTUs 1 and 2, the damper does not respond to setpoint changes. RTUs 3 and 4 do not have economizer setpoints enabled on the controller. All economizers must be functional to complete TAB.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/08/2025 - Mark Johnson - National TAB

Project Issue File Details



12/08/2025