



Comfort. Under control.

10-24 WALGREENS #03606 - SARASOTA,FL

Project Issue Information

Issue Name : Costgard Piping Not Cemented

Description : The PVC Costgard piping is not cemented and can be twisted or separated.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/26/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT0aa843dd07684d3...



Comfort. Under control.

10-24 WALGREENS #03606 - SARASOTA,FL

Project Issue Information

Issue Name : EF-4 Dirty and No Airflow

Description : EXISTING EF-4 serving the liquor restroom is running but not exhausting any air from the space. There is a significant buildup of dust and debris in the fan.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/27/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseITb965c5a2aa81404...



FuseIT326c7eb10f0f473...




Comfort. Under control.

10-24 WALGREENS #03606 - SARASOTA, FL

Project Issue Information

Issue Name : EF-5 Not Running
Description : NEW EF-5 (Liquor Stock) is not running. Unable to locate a thermostat or switch to signal the fan. Liquor manager is not aware of any switches nor has he noticed the fan running at any time.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Originated Date : 10/27/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT7d473f28ea2448b...



Comfort. Under control.

10-24 WALGREENS #03606 - SARASOTA,FL

Project Issue Information

Issue Name : EF-6 Low Flow

Description : EF-6 serving the Women’s RR and the sales floor is low on exhaust flow. The fan data sticker indicates the fan is rated for 500CFM, with the speed controller maximized 547CFM was measured. The original plans indicate a design of 790CFM.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/27/2022 - Stephen Tassinaro - National TAB

Project Issue File Details



FuseIT48021d88cc59492...