

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 02/12/2025
Completed By: National TAB

PROJECT
02-10-25 WAWA #5459 STARKE, FL

103 EDWARDS RD

STARKE, FL 32091

Client

Wawa
260 West Baltimore Pike

Wawa, PA 19063

Issue List

- Diffuser 1-11 - No Damper
- Diffuser 3-1 - No Damper
- EFs - Not Powered
- RTU 1 - Alarm 14
- RTU 2 Returns - No Dampers




02-10-25 WAWA #5459 STARKE, FL


Project Issue Information

Issue Name : Diffuser 1-11 - No Damper
Description : Damper is missing or could not be located for diffuser 1-11 (retail area). Recommend mechanical inspection.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :** SGRD11
Originated Date : 02/12/2025 - Mark Johnson - National TAB

Project Issue File Details



02/12/2025



02/12/2025



02-10-25 WAWA #5459 STARKE, FL

Project Issue Information

Issue Name : Diffuser 3-1 - No Damper
Description : Damper is missing or could not be located for diffuser 3-1 (front vestibule). Recommend mechanical inspection.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :** SGRD1
Originated Date : 02/12/2025 - Mark Johnson - National TAB

Project Issue File Details



02/12/2025



02-10-25 WAWA #5459 STARKE, FL

Project Issue Information

Issue Name : EFs - Not Powered
Description : Exhaust fans are not yet powered. Must be running to allow for balancing.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : Urgent **Asset Tag :** EF1
Originated Date : 02/12/2025 - Mark Johnson - National TAB

Project Issue File Details



02/12/2025



02/12/2025




02-10-25 WAWA #5459 STARKE, FL

Project Issue Information

Issue Name : RTU 1 - Alarm 14
Description : RTU 1 is displaying Alarm 14 - High Pressure Switch Compressor 2. Compressor 2 is locked out. Recommend servicing.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :** RTU1
Originated Date : 02/12/2025 - Mark Johnson - National TAB

Project Issue File Details





02-10-25 WAWA #5459 STARKE, FL

Project Issue Information

Issue Name : RTU 2 Returns - No Dampers
Description : Dampers are not installed or could not be located for RTU 2 return diffusers. Recommend installing to allow for balancing.
Created By : National TAB **Assigned To :** National TAB - Dan Hertenstein
Status : Open
Priority : High **Asset Tag :** RTU2
Originated Date : 02/12/2025 - Mark Johnson - National TAB

Project Issue File Details



02/12/2025



02/12/2025