

Report By:

**National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246**

NATIONAL

TAB

Comfort. Under control.

Report: test

Function: Test, Adjust, & Balance

Date: 11/09/2022

PROJECT

09-12 FIVE GUYS #0420 - HIGHLANDS RANCH, CO (RENEW)

9352 S. COLORADO BLVD

HIGHLANDS RANCH, CO 80126

Client

Five Guys Enterprises LLC
20718 Richmond Highway

Lorton, VA 22079

National TAB

Project: 09-12 FIVE GUYS #0420 - HIGHLANDS RANCH, CO (RENEW)

Table Of Contents

Section	Page #
Checklist Data	3



Comfort. Under control.

09-12 FIVE GUYS #0420 - HIGHLANDS RANCH, CO (RENEW)

CheckList Information

Name : RENEW SITE PICTURES & FINAL BUILDING PERFORMANCE **Status :** NotSubmitted
Assigned Organization : National TAB **Asset :**
Requesting Organization : National TAB


CheckList Item Details

ROOF TOP BEFORE AND AFTER PICTURES

RTU 1 O.A. MESH FILTER (BEFORE AND AFTER)



FuseITca00455fca4e4e4...



FuseIT5ccf7b0876f040c...

RTU 1 FINAL FILTER (BEFORE AND AFTER)



FuseITba2efb61301243b...

RTU 1 CONDENSER COIL (BEFORE AND AFTER)



Clean.jpeg




Dirty(1).jpeg

RTU 1 EVAPORATOR COIL (BEFORE AND AFTER)



Clean.jpeg



Dirty(1).jpeg

RTU 1 - CONDENSATE DRAIN



Drain.jpeg

RTU 1 CONDENSATE PAN



Pan.jpeg

RTU 1 COMBUSITION FAN AND BURNER CONTROLS COMPARTMENT



File.jpeg

RTU 2 OA FILTER (BEFORE AND AFTER)



Clean.jpeg



FuseITe9a2ab575784490...

RTU 2 FINAL FILTER (BEFORE AND AFTER)




FuseITb0dc8ab4733f4cb...




FuseIT61846d6b04de4b3...

RTU 2 CONDENSER COIL (BEFORE AND AFTER)



Dirty(1).jpeg




Clean.jpeg

RTU 2 EVAPORATOR COIL (BEFORE AND AFTER)



Clean.jpeg



Drain.jpeg

RTU 2 CONDENSATE DRAIN



Drain.jpeg



FuseIT731ca7b52207485...

RTU 2 CONDENSATE PAN



Pan.jpeg

RTU 2 COMBUSTION FAN AND BURNER CONTROLS
COMPARTMENT



File.jpeg

RTU 3 OA MESH FILTER (BEFORE AND AFTER)



Degreased.jpeg




FuseIT2911caa3d98445b...

RTU 3 FINAL FILTER (BEFORE AND AFTER)




FuseIT1de223bea78045c...

RTU 3 CONDENSER COIL (BEFORE AND AFTER)



Dirty(1).jpeg



Clean.jpeg

RTU 3 EVAPORATOR COIL (BEFORE AND AFTER)



Dirty(1).jpeg




Clean.jpeg

RTU 3 CONDENSATE DRAIN




FuseITfb273086343d4b1...

RTU 3 CONDENSATE PAN



Pan.jpeg

RTU 3 COMBUSITION FAN AND BURNER CONTROLS
COMPARTMENT



File.jpeg

MUA FAN BEFORE AND AFTER PICTURES

MUA OA MESH FILTERS



Clean.jpeg




FuselTc25da33ede53424...

MUA BLOWER/MOTOR COMPARTMENT



MUA HEATER CONTROLS COMPARTMENT



EXHAUST FAN BEFORE AND AFTER PICTURES

EXHAUST FAN KEF1 MOTOR HOUSING CLEANED



EXHAUST FAN KEF1 GREASE CUP PROPERLY INSTALLED



FuseITd618fbcc785f41e...

EXHAUST FAN KEF2 MOTOR HOUSING CLEANED



FuseIT7b25fc58806940c...

EXHAUST FAN KEF2 GREASE CUP PROPERLY INSTALLED



FuseIT2c3a3cc7923143c...

Notes/Comments :