

PlanGrid Task Report - Mar 9, 2026

Prepared by Dale Wheeler

Mar 9, 2026

Description

12 tasks in this report.

Contents

#39 [REFG 501] [NEW] WIC/WIF evaporator fans.	2
#38 [REFG 516] [NEW] Condenser electrical disconnects.	3
#37 [UNIT 522] [NEW] AC air filters.	4
#36 [REFG 505] [NEW] WIC door sweep vs threshold.	5
#35 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.....	6
#34 [REFG 508] [NEW] WIC/WIF panel penetrations.....	7
#32 [CNTL 999] [NEW] (MISC) [TF2 Thermostat].....	8
#24 [EXHA 507] [NEW] Exhaust fan drain line.....	10
#23 [EXHA 508] [NEW] Exhaust fan G2 Drip Guard.....	11
#20 [CURT 501] [NEW] Air curtain power.	12
#19 [CNTL 508] [NEW] Controls labeling.....	13
#16 [CNTL 509] [NEW] Ansul pull labeling.....	15

#39 [REFG 501] [NEW] WIC/WIF evaporator fans.

Status

Open

Start Date

Feb 6, 2026

Type

Planned Work

Created

Mar 9, 2026 9:43 AM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 9:43 AM

Description

WIF & WIC evap fans are not operational at time of TAB. Unable to test WIF & WIC box temperatures.

#38 [REFG 516] [NEW] Condenser electrical disconnects.

Status

Open

Start Date

Mar 5, 2026

Type

Planned Work

Created

Mar 5, 2026 12:11 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 7:54 AM

Description

WIF & WIC disconnects
need labeled

Photos



IMG_0242
Dale Wheeler
Mar 5, 2026 12:12 PM



IMG_0243
Dale Wheeler
Mar 5, 2026 12:12 PM

L06012_Wendell Falls FSU (NC)

2100 Treelight Way, Wendell, North Carolina

L1020006012

#37 [UNIT 522] [NEW] AC air filters.

Status

Open

Start Date

Mar 5, 2026

Type

Planned Work

Created

Mar 5, 2026 12:11 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 7:56 AM

Description

Extra set of filters is not on site for AC1, AC2, AC3, AC4, AC5.

#36 [REFG 505] [NEW] WIC door sweep vs threshold.

Status

Open

Start Date

Mar 5, 2026

Type

Planned Work

Created

Mar 5, 2026 12:10 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 7:57 AM

Description

WIC door sweep is not sealed tightly with threshold when door is closed. Only translucent light should be present inspecting from the inside out with box lights off.

Photos



IMG_0248

Dale Wheeler

Mar 5, 2026 12:10 PM

#35 [REFG 511] [NEW] PVC pipe chase (gooseneck) installation.

Status

Open

Start Date

Mar 5, 2026

Type

Planned Work

Created

Mar 5, 2026 12:09 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 7:58 AM

Description

-WIF & WIC gooseneck openings need to be sealed with spray foam & caulk.

Photos



IMG_0240

Dale Wheeler

Mar 5, 2026 12:09 PM



IMG_0241

Dale Wheeler

Mar 5, 2026 12:09 PM

#34 [REFG 508] [NEW] WIC/WIF panel penetrations.

Status

Open

Start Date

Mar 5, 2026

Type

Planned Work

Created

Mar 5, 2026 12:08 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:03 AM

Description

WIC & WIF lines need to be sealed on top of the boxes.

Photos



IMG_0252

Dale Wheeler

Mar 5, 2026 12:08 PM



IMG_0251

Dale Wheeler

Mar 5, 2026 12:08 PM

#32 [CNTL 999] [NEW] (MISC) [TF2 Thermostat]

Status

Open

Start Date

Mar 5, 2026

Type

Planned Work

Created

Mar 5, 2026 12:06 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:13 AM

Description

TF2 7 day programable thermostat & rib relay are not installed at time of TAB.

Photos

L06012_Wendell Falls FSU (NC)

2100 Treelight Way, Wendell, North Carolina

L1020006012



IMG_0255

Dale Wheeler

Mar 5, 2026 12:06 PM

L06012_Wendell Falls FSU (NC)

2100 Treelight Way, Wendell, North Carolina

L1020006012

#24 [EXHA 507] [NEW] Exhaust fan drain line.

Status

Open

Start Date

Mar 3, 2026

Type

Planned Work

Created

Mar 3, 2026 10:18 AM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:07 AM

Description

EF1 & EF2 drip guard drains need to be installed.

Photos



20260303_091919_photo

Dale Wheeler

Mar 3, 2026 10:19 AM



20260303_091911_photo

Dale Wheeler

Mar 3, 2026 10:19 AM

#23 [EXHA 508] [NEW] Exhaust fan G2 Drip Guard.

Status

Open

Start Date

Mar 3, 2026

Type

Planned Work

Created

Mar 3, 2026 10:17 AM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:06 AM

Description

EF1 & EF2 drip guards need to be installed.

Photos



20260303_091820_photo

Dale Wheeler

Mar 3, 2026 10:18 AM



20260303_091810_photo

Dale Wheeler

Mar 3, 2026 10:18 AM

#20 [CURT 501] [NEW] Air curtain power.

Status

Open

Start Date

Mar 2, 2026

Type

Planned Work

Created

Mar 2, 2026 6:39 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:10 AM

Description

AD1 & AD2 air curtains were not operational.

Photos



20260302_174101_photo

Dale Wheeler

Mar 2, 2026 6:41 PM



20260302_174010_photo

Dale Wheeler

Mar 2, 2026 6:40 PM

L06012_Wendell Falls FSU (NC)

2100 Treelight Way, Wendell, North Carolina

L1020006012

#19 [CNTL 508] [NEW] Controls labeling.

Status

Open

Start Date

Mar 2, 2026

Type

Planned Work

Created

Mar 2, 2026 6:32 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:12 AM

Description

AC1, AC2, AC3, AC4, AC5
temp. & humidity sensors
need labeled.

Photos

L06012_Wendell Falls FSU (NC)

2100 Treelight Way, Wendell, North Carolina

L1020006012



20260302_173252_photo

Dale Wheeler

Mar 2, 2026 6:32 PM

L06012_Wendell Falls FSU (NC)

2100 Treelight Way, Wendell, North Carolina

L1020006012

#16 [CNTL 509] [NEW] Ansul pull labeling.

Status

Open

Start Date

Mar 2, 2026

Type

Planned Work

Created

Mar 2, 2026 4:08 PM
dale@nationaltab.com

List

TAB Punch List

Last Updated

Mar 9, 2026 8:09 AM

Description

Ansul pull stations need labeled.

Photos



20260302_150847_photo

Dale Wheeler

Mar 2, 2026 4:08 PM