

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 07/08/2024

PROJECT

07-08-24 WAWA #05803 ROBERTSDALE, AL

21022 HWY 59 BALDWIN

ROBERTSDALE, AL 36567

Client

Wawa
260 West Baltimore Pike
Wawa, PA 19063

Issue List

- Diffuser 1-13 Missing Grille
- EF 2 - Speed Controller Not Functional
- RTU 3 - Economizer Not Functional



07-08-24 WAWA #05803 ROBERTSDALE, AL

Project Issue Information

Issue Name : Diffuser 1-13 Missing Grille
Description : Diffuser 1-13 (rear vestibule) is missing the grille. Recommend installing per mechanical plans.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 07/08/2024 - Mark Johnson - National TAB

Project Issue File Details



IMG_0614
07/08/2024



07-08-24 WAWA #05803 ROBERTSDALE, AL

Project Issue Information

Issue Name : EF 2 - Speed Controller Not Functional
Description : The speed controller for EF 2 (in-line, above cooler) does not appear to be modulating the fan's speed. Fan remains running when controller is switched off. Recommend verifying controller wiring.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : High **Asset Tag :**
Originated Date : 07/08/2024 - Mark Johnson - National TAB



07-08-24 WAWA #05803 ROBERTSDALE, AL

Project Issue Information

Issue Name : RTU 3 - Economizer Not Functional
Description : The economizer for RTU 3 is not responding to setting changes through CORE. Alarm 137 - "Damper Stuck Closed" appears and the damper will not open. Must be corrected for proper balancing.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 07/08/2024 - Mark Johnson - National TAB

Project Issue File Details

