

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Deficiency Report
Function: Test, Adjust, & Balance
Date: 04/08/2024

PROJECT
04-01-24 CHUY'S - MUELLER, TX

971 Farmington Ave

West Hartford, CT 06107

Client

CORNERSTONE COMMERCIAL
PO BOX 703568
DALLAS, TX 75370

Issue List

- Diffuser 11-3 Damaged
- Hood 1 Damaged Filter
- Thermostat Wiring



04-01-24 CHUY'S - MUELLER, TX

Project Issue Information

Issue Name : Diffuser 11-3 Damaged
Description : Diffuser 11-3 is damaged and the perforated cover is falling off as a result. NTi reinstalled the cover several times throughout the day. Recommend repair/replacement.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 04/08/2024 - Stephen Tassinaro - National TAB

Project Issue File Details



**Diffuser11_3
04/08/2024**



**IMG_2597
04/08/2024**




04-01-24 CHUY'S - MUELLER, TX

Project Issue Information

Issue Name : Hood 1 Damaged Filter
Description : Hood 1 has a damaged grease filter, it is not effecting performance in any way.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : InfoOnly **Asset Tag :**
Originated Date : 04/08/2024 - Stephen Tassinaro - National TAB

Project Issue File Details



IMG_2596
04/08/2024



04-01-24 CHUY'S - MUELLER, TX

Project Issue Information

Issue Name : Thermostat Wiring
Description : It was found that the thermostats are have wires landed at the humidity terminals and two additional sensor terminals, however no remote sensors are enabled on the thermostats. The stats are running off their own internal sensors only.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : High **Asset Tag :**
Originated Date : 04/08/2024 - Stephen Tassinaro - National TAB

Project Issue File Details



IMG_2595
04/08/2024



IMG_2594
04/08/2024