

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Punchlist
Function: Test, Adjust, & Balance
Date: 10/08/2025
Completed By: National TAB

PROJECT
10-06-25 CAVA NEWTOWN, PA

2938 EAGLE RD

NEWTOWN, PA 18940

Client

CAVA
702 H ST NW
2nd floor
Washington, DC 20001

National TAB

Project: 10-06-25 CAVA NEWTOWN, PA

Table Of Contents

Section	Page #
Remarks	3

Issue List

- HD1: Caulking Degraded
- HD1: Grease Cups Not Installed
- HD1: Hood End Panel Not Installed
- HD1: MISSING TEMPT SENS #03
- KEF1: Grease Cup Not Installed
- KEF1: Hinge Kit Not Installed
- MAU1: Gas Valve Closed
- RTU1: Economizer Not Functional
- RTU2: Vibration Issue



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : HD1: Caulking Degraded
Description : Hood caulking to wall on back, side, and front has degraded. Gaps can accumulate grease. Recaulk.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : HD1: Grease Cups Not Installed
Description : Grease cups not installed on hood. Find or order and install.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : HD1: Hood End Panel Not Installed
Description : Install according to manufacturer directions.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : HD1: MISSING TEMPT SENS #03
Description : Hood is showing a fault called Missing Temp Sens #03. Troubleshoot and repair according to manufacturer guidance.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : KEF1: Grease Cup Not Installed
Description : Grease cup not installed on KEF1 curb. Install according to manufacturer instructions.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : KEF1: Hinge Kit Not Installed
Description : Hinge kit for KEF1 not installed. Install according to manufacturer directions.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : High **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : MAU1: Gas Valve Closed
Description : Gas valve for MAU1 is closed. Open valve and perform burner startup.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : Low **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : RTU1: Economizer Not Functional
Description : Economizer of RTU2 not functional. Unable to set OA. Service according to manufacturer guidance.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : High **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025



10-06-25 CAVA NEWTOWN, PA

Project Issue Information

Issue Name : RTU2: Vibration Issue
Description : RTU2 vibrates loudly. Vibrations are strong enough to work belt loose overnight. Service according to manufacturer guidance.
Created By : National TAB **Assigned To :** National TAB - Brianna Biggs
Status : Open
Priority : High **Asset Tag :**
Originated Date : 10/08/2025 - Ryan Smith - National TAB

Project Issue File Details



10/08/2025