

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: TAB Punchlist
Function: Test, Adjust, & Balance
Date: 12/18/2024
Completed By: National TAB

PROJECT

Springer School Addition (Cincinnati, OH)

2121 Madison Rd

Cincinnati, OH

Client

Feldkamp Enterprises
3642 Muddy Creek Rd
Cincinnati, OH 45238

National TAB

Project: Springer School Addition (Cincinnati, OH)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- DOAS Powering Off Intermittently
- FC-100 No Damper
- FC-101 No Damper
- FC-201 Missing Diffuser
- FC-204 No Damper
- FC-212 No Damper
- FC-225 No Damper
- FC-306 Not Ducted



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : DOAS Powering Off Intermittently
Description : Fan stops spinning randomly during operation. It appears to re-start without any resetting.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-100 No Damper
Description : Damper for FC-100 is not installed. Diffuser is above design.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-101 No Damper
Description : Damper for FC-101 is not installed. Diffuser is above design.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-201 Missing Diffuser
Description : OA duct intended for area/unit 201 is present but there is no diffuser installed.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-204 No Damper
Description : Damper for FC-204 is not installed. Diffuser is above design.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-212 No Damper
Description : Damper for FC-212 is not installed. Diffuser is above design.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-225 No Damper
Description : Damper for FC-225 is not installed. Diffuser is above design.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB



Springer School Addition (Cincinnati, OH)

Project Issue Information

Issue Name : FC-306 Not Ducted
Description : FC-306 is not ducted to the DOAS unit therefore is not receiving any supply air.
Created By : National TAB **Assigned To :** National TAB - Jordan Best
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 12/18/2024 - Jordan Best - National TAB