

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: TAB Punchlist**  
**Function: Test, Adjust, & Balance**  
**Date: 12/18/2024**  
**Completed By: National TAB**

# PROJECT

## Springer School Addition (Cincinnati, OH)

2121 Madison Rd

Cincinnati, OH

### Client

Feldkamp Enterprises  
3642 Muddy Creek Rd  
Cincinnati, OH 45238

# National TAB

Project: Springer School Addition (Cincinnati, OH)

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- DOAS Powering Off Intermittently
- EF-2 Below Design
- EF-3 Above Design
- FC-100 No Damper
- FC-101 Below Design
- FC-101 No Damper
- FC-201 Missing Diffuser
- FC-204 No Damper
- FC-212 No Damper
- FC-225 No Damper
- FC-306 Not Ducted



### Springer School Addition (Cincinnati, OH)

#### Project Issue Information

**Issue Name :** DOAS Powering Off Intermittently  
**Description :** Fan stops spinning randomly during operation. It appears to re-start without any resetting.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



## Springer School Addition (Cincinnati, OH)

### Project Issue Information

**Issue Name :** EF-2 Below Design  
**Description :** EF-2 is operating below design. The unit is equipped with no speed controller and is operating at its highest speed.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 12/19/2024 - Jordan Best - National TAB



## Springer School Addition (Cincinnati, OH)

### Project Issue Information

**Issue Name :** EF-3 Above Design  
**Description :** EF-3 is operating above design. The unit is not equipped with a speed controller and the fan speed cannot be decreased.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 12/19/2024 - Jordan Best - National TAB



### Springer School Addition (Cincinnati, OH)

#### Project Issue Information

**Issue Name :** FC-100 No Damper  
**Description :** Damper for FC-100 is not installed. Diffuser is above design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



### Springer School Addition (Cincinnati, OH)

#### Project Issue Information

**Issue Name :** FC-101 Below Design  
**Description :** FC-101 is operating below design. The fan is operating at its highest set point and cannot be increased. Diffusers are balanced proportionately low.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 12/19/2024 - Jordan Best - National TAB



**Springer School Addition (Cincinnati, OH)**

**Project Issue Information**

**Issue Name :** FC-101 No Damper  
**Description :** Damper for FC-101 is not installed. Diffuser is above design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



## Springer School Addition (Cincinnati, OH)

### Project Issue Information

**Issue Name :** FC-201 Missing Diffuser  
**Description :** OA duct intended for area/unit 201 is present but there is no diffuser installed.  
**Created By :** National TAB      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



## Springer School Addition (Cincinnati, OH)

### Project Issue Information

**Issue Name :** FC-204 No Damper  
**Description :** Damper for FC-204 is not installed. Diffuser is above design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



## Springer School Addition (Cincinnati, OH)

### Project Issue Information

**Issue Name :** FC-212 No Damper  
**Description :** Damper for FC-212 is not installed. Diffuser is above design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



### Springer School Addition (Cincinnati, OH)

#### Project Issue Information

**Issue Name :** FC-225 No Damper  
**Description :** Damper for FC-225 is not installed. Diffuser is above design.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB



## Springer School Addition (Cincinnati, OH)

### Project Issue Information

**Issue Name :** FC-306 Not Ducted  
**Description :** FC-306 is not ducted to the DOAS unit therefore is not receiving any supply air.  
**Created By :** National TAB                      **Assigned To :** National TAB - Jordan Best  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 12/18/2024 - Jordan Best - National TAB