

CHILI'S MERRITT PARK - DUNDALK, MD

Issue Summary

Unit	Issue Name	Priority	Description
Hood PSP's	Hood PSP's are dirty and need cleaning	High	MUA PSP's (perforated sheet metal at hood's) are dirty and restricting airflow. The building is currently highly negative as a result until this is resolved. They need to be DROPPED down and the tops cleaned. Not just cleaning the bottoms.
MUA	Intake air filters are dirty	High	The mesh intake air filters for the MUA are dirty and need to be cleaned.
EF-2	EF-2 speed controller not installed	Low	Speed controller not present. Recommend installing
EF-3	EF-3 speed controller not functional	Med	The speed controller for EF-3 does not respond to adjustment and needs to be replaced.
RTU-3	RTU-3 Alarms	Med	RTU-3 is giving Alarms 60 and 91. After powercycling the unit, Alarm 91 remained.
RTU-1	RTU-1 Alarms	Med	RTU1 is giving alarms 139 and 147.

