

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: PUNCHLIST**  
**Function: Test, Adjust, & Balance**  
**Date: 01/15/2026**  
**Completed By: National TAB**

**PROJECT**  
**01-12-26 QT #0585 OMAHA, NE**

4720 HAMILTON STREET

OMAHA, NE

**Client**

QUIKTRIP  
4705 SOUTH 129TH EAST AVENUE  
TULSA, OK 74134

# National TAB

Project: 01-12-26 QT #0585 OMAHA, NE

## Table Of Contents

Section	Page #
Issue Data	3

## Issue List

- EF-1: Missing Belt
- EF-1: Motor Cover/Housing
- RT-1: GFI Outlet Cover
- RT-2: Low Airflow
- RT-2: OA Damper Actuator
- RT-2: Return Damper Blade
- RT-2: Whistling Sound



01-12-26 QT #0585 OMAHA, NE

Project Issue Information

**Issue Name :** EF-1: Missing Belt  
**Description :** The drive belt for EF-1 is missing. No airflow.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :** EF1  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026



**01-12-26 QT #0585 OMAHA, NE**

**Project Issue Information**

**Issue Name :** EF-1: Motor Cover/Housing  
**Description :** The motor cover/housing is not securely fastened to the base of the fan.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Low                                      **Asset Tag :** EF1  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026



**01-12-26 QT #0585 OMAHA, NE**

**Project Issue Information**

**Issue Name :** RT-1: GFI Outlet Cover  
**Description :** The GFI outlet cover for RT-1 is not securely attached to the unit. Placed Cover over GFI outlet. Plastic tabs are broken and cover was found laying on the roof upon arrival.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Low                                      **Asset Tag :** RT-1  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026



**01-12-26 QT #0585 OMAHA, NE**

**Project Issue Information**

**Issue Name :** RT-2: Low Airflow  
**Description :** RT-2 is low on airflow. Measured 3228 CFM. Design is 4,000 CFM. Adjusted motor sheave as far as possible. Set OA proportional to Supply airflow.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** High                                      **Asset Tag :** RT-2  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026



01-12-26 QT #0585 OMAHA, NE

**Project Issue Information**

**Issue Name :** RT-2: OA Damper Actuator  
**Description :** The OA damper actuator is not attached to the damper blades. OA damper position set manually.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :** RT-2  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026



01-12-26 QT #0585 OMAHA, NE

**Project Issue Information**

**Issue Name :** RT-2: Return Damper Blade  
**Description :** A return damper blade is broken. Blade is detached from side wall.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Medium                                      **Asset Tag :** RT-2  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026



**01-12-26 QT #0585 OMAHA, NE**

**Project Issue Information**

**Issue Name :** RT-2: Whistling Sound  
**Description :** RT-2 has loud whistling sound coming from blower compartment door. Issue seems to be cause by bad seal.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** Low                                      **Asset Tag :** RT-2  
**Originated Date :** 01/15/2026 - Kalen Kemp - National TAB

Project Issue File Details



01/15/2026