

TAB Punch List CFA 01920 Fairlawn OH

Prepared by Cody Collett

Sep 22, 2025

Description

15 tasks in this report.

Contents

#247 [SITE 005] [EXIST] CRITICAL – Ceiling grid / tiles.	2
#246 [EXHA 005] [EXIST] CRITICAL – Restroom fan damper.	3
#245 [EXHA 006] [EXIST] CRITICAL – Restroom fan speed controller.	4
#244 [EXHA 009] [EXIST] CRITICAL – Restroom EF ductwork.	5
#243 [HOOD 007] [EXIST] CRITICAL – CJ fans.....	5
#242 [DUCT 012] [EXIST] CRITICAL – Damper(s) missing or inaccessible.....	6
#241 [DUCT 016] [EXIST] CRITICAL – Duct is restricted – dimensional.....	6
#240 [EXHA 508] [EXIST] Exhaust fan G2 Drip Guard.	8
#239 [EXHA 510] [EXIST] Grease exhaust duct is not supported.	10
#238 [HOOD 504] [EXIST] Hood angled trim.....	10
#237 [HOOD 511] [EXIST] Hood 1L/1R hardware.	12
#236 [HOOD 512] [EXIST] Grease cup and fry chute.....	13
#235 [UNIT 517] [EXIST] Condensate piping construction.	15
#234 [UNIT 524] [EXIST] Equipment cabinets need cleaning.....	16
#233 [UNIT 532] [EXIST] Equipment belt tensioner.	17

#247 [SITE 005] [EXIST] CRITICAL – Ceiling grid / tiles.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Ceiling grid is not fully installed or excessive tiles are missing at time of TAB inspection, unable to obtain accurate building pressure.

#246 [EXHA 005] [EXIST] CRITICAL – Restroom fan damper.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:13 PM

List

TAB Punch List

Description

Restroom fan backdraft damper is not installed properly or does not move freely. Unable to accurately balance system until corrected.

Photos



IMG_1127

Cody Collett

Sep 15, 2025 2:55 PM

#245 [EXHA 006] [EXIST] CRITICAL – Restroom fan speed controller.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Restroom fan speed controller is not installed or is not operational. Unable to

accurately balance system until corrected.

#244 [EXHA 009] [EXIST] CRITICAL – Restroom EF ductwork.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Restroom EF ductwork, fan blade, and/or back draft damper is dirty and needs to be cleaned.

#243 [HOOD 007] [EXIST] CRITICAL – CJ fans.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Hood CJ fan ductwork, intake grilles, and/or fan blades needs to be cleaned.

#242 [DUCT 012] [EXIST] CRITICAL – Damper(s) missing or inaccessible.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Damper(s) not installed at branch location or on run-out on plans, or is installed in a way that is inaccessible by the TAB technician. Unable to balance system until corrected. AC-3 diffuser 1 damper handle broken, AC-3 diffuser 4 no damper installed. AC-2 two dampers actuate but do not affect airflow on any return grills (located in above managers office ceiling.)

#241 [DUCT 016] [EXIST] CRITICAL – Duct is restricted – dimensional.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Duct is crushed or constructed in a way that impedes proper airflow. Ensure inside clear dimensions are maintained according to floor plan or detail for system and is constructed per SMACNA guidelines with bracing if required. Unable to balance until corrected. (AC-1 Return ductwork.)

#240 [EXHA 508] [EXIST] Exhaust fan G2 Drip Guard.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:14 PM

List

TAB Punch List

Description

Exhaust fan G2 Drip Guard
is not installed correctly or is
missing.

Photos

01920 Montrose // Fairlawn, OH // 2025

47 Flight Memorial Drive, Akron, Ohio

L2220201920



IMG_1101
Cody Collett
Sep 15, 2025 1:35 PM



IMG_1095
Cody Collett
Sep 15, 2025 1:31 PM

#239 [EXHA 510] [EXIST] Grease exhaust duct is not supported.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:15 PM

List

TAB Punch List

Description

Exhaust duct is to be supported per kitchen hood exhaust fan detail on 6'0" centers.

Photos



IMG_1093
Cody Collett
Sep 15, 2025 1:28 PM



IMG_1092
Cody Collett
Sep 15, 2025 1:28 PM

#238 [HOOD 504] [EXIST] Hood angled trim.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

01920 Montrose // Fairlawn, OH // 2025

47 Flight Memorial Drive, Akron, Ohio

L2220201920

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Hood has poorly installed or missing angled trim that is to be installed and sealed to FRP.

#237 [HOOD 511] [EXIST] Hood 1L/1R hardware.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:16 PM

List

TAB Punch List

Description

Hoods 1L/1R are missing bolting hardware and / or the splice brackets that are to be installed at their midpoint connection seams. (Missing screws for multiple access panels, HD1R-HD1L splice bracket is broken and half is missing.)

Photos



IMG_1136

Cody Collett

Sep 16, 2025 7:36 AM

#236 [HOOD 512] [EXIST] Grease cup and fry chute.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:21 PM

List

TAB Punch List

Description

Hoods are missing their grease cups and / or fry chutes. (Grease cup HD-2.)

01920 Montrose // Fairlawn, OH // 2025

47 Flight Memorial Drive, Akron, Ohio

L2220201920

(Fry Chutes HD-2 and
HD-3.)

#235 [UNIT 517] [EXIST] Condensate piping construction.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:18 PM

List

TAB Punch List

Description

Equipment condensate piping or p-trap is not constructed per normal CFA specifications.

Photos



IMG_1159

Cody Collett

Sep 17, 2025 12:51 PM

#234 [UNIT 524] [EXIST] Equipment cabinets need cleaning.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:08 PM

List

TAB Punch List

Description

Equipment cabinets are dirty and needs to be cleaned.

#233 [UNIT 532] [EXIST] Equipment belt tensioner.

Status

Open

Created

Sep 22, 2025 8:08 PM
codyc@nationaltab.com

Type

Planned Work

Last Updated

Sep 22, 2025 8:19 PM

List

TAB Punch List

Description

Equipment belt tensioner is defective and needs to be replaced. (EF-1 and EF-2)
