

## Issue List

- EF-11 Not Operational
- EF-12 Not Operational
- EF-14 Not Operational
- EF-15 Not Operational
- EF-17 Rotation Backwards
- EF-19 Not Operational
- EF-23 High Flow
- EF-23 Missing Grille
- EF-26 Low Flow
- EF-3 Not operational and Motor Damper not wired
- EF-4 High Flow
- EF-4 Noise at Fan
- EF-9 Not Operational
- Hanger EFs Not Operational
- Incorrect Connected Return Grille
- Incorrectly Installed Duct for Return
- Missing Damper for Return Grille
- Missing Damper for Return Grille in E107
- Missing Multiple Return Dampers in ROOM READY/BREAKROOM N151
- Missing Return Damper for CORRIDOR N153
- Missing Return Damper in OPEN OFFICE E123
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153A
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153C
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153E

- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153F
- Missing Return Damper in ROOM AVIONICS ELEMENT CHIEF N116
- Missing Return Damper in ROOM AXMS CHIEF N153B
- Missing Return Damper in ROOM CLASSROOM E108
- Missing Return Damper in ROOM CMF CHIEF N117
- Missing Return Damper in ROOM COMMANDER N141
- Missing Return Damper in ROOM COMSEC N110AA
- Missing Return Damper in ROOM CONFERENCE N118
- Missing Return Damper in ROOM CTK N131
- Missing Return Damper in ROOM ENG ELEMENT CHIEF N113A
- Missing Return Damper in Room PRO SUP N144
- Missing Return Damper in ROOM SHIRT OFFICE N143
- Missing Return Damper in ROOM SIPR N110A
- Missing Return Dampers in Offices
- Missing Return Dampers in ROOM AVIONICS N110
- MUA-2 Dirty Filters
- Multiple Dampers Missing HANGER SHOP NORTH
- Multiple Return Dampers missing
- PAH-1 Stages Issues
- Return Damper Missing in ROOM MOO 142



### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** EF-11 Not Operational  
**Description :** EF-11 motor sheave unscrewed itself and damaged the belt.  
Recommended to repair and replace  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/09/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/09/2026



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** EF-12 Not Operational

**Description :** EF-12 motor sheave unscrewed itself and damaged the belt.  
Recommended to repair and replace belt.

**Created By :** National TAB

**Assigned To :** National TAB - Antonio Flores-De La Cruz

**Status :** Open

**Priority :** Urgent

**Asset Tag :**

**Originated Date :** 03/09/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/09/2026



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** EF-14 Not Operational

**Description :** EF-14 is not operational because the motor sheave and belt are damaged. The motor sheave broke into two pieces.

**Created By :** National TAB

**Assigned To :** National TAB - Antonio Flores-De La Cruz

**Status :** Open

**Priority :** Urgent

**Asset Tag :**

**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** EF-15 Not Operational

**Description :** EF-15 shaft to the blower is not connected at this time.

**Created By :** National TAB

**Assigned To :** National TAB - Antonio Flores-De La Cruz


**Status :** Open

**Priority :** Urgent

**Asset Tag :**

**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** EF-17 Rotation Backwards  
**Description :** EF-17 is running but rotation is backwards. Must correct to TAB  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/09/2026 - Antonio Flores-De La Cruz - National TAB



### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** EF-19 Not Operational  
**Description :** EF-19 is not operational. Disconnect, motor starter, and breaker are all on. Motor starter shows a stall fault code (HAND & AUTO FLASHING)  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/09/2026 - Antonio Flores-De La Cruz - National TAB



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** EF-23 High Flow  
**Description :** EF-23 is 37% above design (407 CFM ACTUAL / 300 CFM DESIGN) and requires a sheave change to reduce flow. Motor sheave is on the lowest setting. Unable to balance due to a diffuser missing as well.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** EF-23 Missing Grille  
**Description :** Grille EF-23-1 in JANITORS E118 is not installed.  
**Created By :** National TAB  
**Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** High  
**Asset Tag :**  
**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



02/12/2026



02/12/2026



02/12/2026



### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** EF-26 Low Flow  
**Description :** EF-26 is at 66% of design (99 CFM ACTUAL / 150 CFM DESIGN). The speed dial is at max. A possible cause could be a partially opened exhaust motorized damper. It was found that there is a damper at the takeoff and one at the arm of the equipment where the duct connects, which may add resistance to the system.

**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz

**Status :** Open

**Priority :** Urgent                                      **Asset Tag :**

**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



02/12/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** EF-3 Not operational and Motor Damper not wired  
**Description :** The exhaust damper for EF-3 is not wired, and Controls stated that the fan is not wired to be operational.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



02/12/2026

#### Project Issue Response Details

- **03/10/2026**    **National TAB - Antonio Flores-De La Cruz**
  - Manually opened the exhaust damper and balanced

---

- **03/05/2026**    **National TAB - Antonio Flores-De La Cruz**
  - FAN APPEARS WIRED, BUT DAMPER IS STILL NOT WIRED TO OPEN.



## NCANG Repair Bldg 51 (Charlotte, NC)

### Project Issue Information

**Issue Name :** EF-4 High Flow  
**Description :** EF-4 is 18% above design (706 CFM ACTUAL / 600 CFM DESIGN) and requires a sheave change to reduce flow. Motor sheave is on the lowest setting. Grilles are balanced proportionally high.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 02/10/2026 - Antonio Flores-De La Cruz - National TAB



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** EF-4 Noise at Fan  
**Description :** One of the fan blades is grinding against the housing of the fan.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** [Medium](#)                      **Asset Tag :**  
**Originated Date :** 02/10/2026 - Antonio Flores-De La Cruz - National TAB



### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** EF-9 Not Operational  
**Description :** EF-9 is currently not running. It is on at the disconnect, the motor starter, and the lower disconnect switch. Controls are commanding it to run.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/09/2026 - Antonio Flores-De La Cruz - National TAB



**NCANG Repair Bldg 51 (Charlotte, NC)**

**Project Issue Information**

**Issue Name :** Hanger EFs Not Operational  
**Description :** EF-9 through EF-19, EXCEPT EF-13, are not operational. Controls stated the exhaust fans might be wired incorrectly. Further investigation is required.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue Response Details

- **03/05/2026    National TAB - Antonio Flores-De La Cruz**
  - MECHANICAL STATED ALL BUT EF-9, EF-14, AND EF-15 ARE OPERATIONAL NOW. WILL CHECK AND TAB





### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Incorrect Connected Return Grille  
**Description :** Return Grille R1N-34 is connected to the supply, not the return.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details






### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Incorrectly Installed Duct for Return  
**Description :** Grilles R1N-28 and R1N-29 were attached to EF-22 ductwork.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026



### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Damper for Return Grille  
**Description :** Return Grille R2E-7 in E107A is missing the damper to balance.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/02/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/02/2026



03/02/2026



### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Damper for Return Grille in E107  
**Description :** Grille R2E-8 is missing the damper to balance.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/02/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/02/2026



03/02/2026



### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Multiple Return Dampers in ROOM READY/BREAKROOM N151  
**Description :** Return grilles: R1N-15, R1N-16, R1N-23, and R1N-24 are all missing dampers to TAB.


**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz

**Status :** Open

**Priority :** **Urgent**                                      **Asset Tag :**

**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details






### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper for CORRIDOR N153  
**Description :** Grille R1N-21 is missing the damper ot TAB.  
**Created By :** National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent** **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in OPEN OFFICE E123  
**Description :** Damper for Grille R2E-15 is missing to balance.  
**Created By :** National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent **Asset Tag :**  
**Originated Date :** 03/02/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/02/2026



03/02/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153A  
**Description :** Grille R1N-22 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153C  
**Description :** Grille R1N-19 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153F  
**Description :** Grille R1N-18 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM AVIONICS ELEMENT CHIEF N116  
**Description :** Grille R1N-8 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details






### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM AXMS CHIEF N153B  
**Description :** Grille R1N-20 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM CLASSROOM E108  
**Description :** Damper for Grille R2E-14 in ROOM CLASSROOM E108 is missing to balance.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/02/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details






### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM CMF CHIEF N117  
**Description :** Grille R1N-9 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details






### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM COMMANDER N141  
**Description :** Grille R1N-17 is missing the return damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM COMSEC N110AA  
**Description :** Grille R1N-5 is missing the damper to TAB.  
**Created By :** National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM CONFERENCE N118  
**Description :** Grille R1N-10 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM CTK N131  
**Description :** Grille R1N-30 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM ENG ELEMENT CHIEF N113A  
**Description :** Grille R1N-12 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in Room PRO SUP N144  
**Description :** Return Damper for Grille R1N-45 is missing to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026



### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM SHIRT OFFICE N143  
**Description :** Grille R1N-14 is missing the return damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026



### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Damper in ROOM SIPR N110A  
**Description :** Grille R1N-4 is missing the damper to TAB.  
**Created By :** National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Missing Return Dampers in Offices  
**Description :** Grilles R2E-12 and R2E-13 are missing their dampers to balance the return.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/02/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details





### NCANG Repair Bldg 51 (Charlotte, NC)


#### Project Issue Information

**Issue Name :** Missing Return Dampers in ROOM AVIONICS N110  
**Description :** Grilles R1N-6 and R1N-7 are missing the dampers to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026



### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** MUA-2 Dirty Filters

**Description :** MUA-2 filters are dirty and must be changed to TAB.

**Created By :** National TAB

**Assigned To :** National TAB - Antonio Flores-De La Cruz

**Status :** Open

**Priority :** Urgent

**Asset Tag :**

**Originated Date :** 02/12/2026 - Antonio Flores-De La Cruz - National TAB




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Multiple Dampers Missing HANGER SHOP NORTH  
**Description :** Return Grilles R1N-31 through R1N-37, EXCEPT R1N-34, are missing dampers to balance the return.  
**Created By :** National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** Urgent **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026



03/03/2026




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Multiple Return Dampers missing  
**Description :** Dampers for Return Grilles: RE2-1 through RE2-5 are missing to balance.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/02/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/02/2026



03/02/2026



## NCANG Repair Bldg 51 (Charlotte, NC)

### Project Issue Information

**Issue Name :** PAH-1 Stages Issues

**Description :** PAH-1 is having issues with selecting stages, specifically heating. Unit is only going into Cooling, no heating. Controls is going to get access to the communications room from the Military, and he will see what's going on with the TSAT, but stated it could be a mechanical/service issue. WINTER LAT/EAT is needed.

**Created By :** National TAB

**Assigned To :** National TAB - Antonio Flores-De La Cruz

**Status :** Open

**Priority :** Urgent

**Asset Tag :**

**Originated Date :** 03/10/2026 - Antonio Flores-De La Cruz - National TAB




### NCANG Repair Bldg 51 (Charlotte, NC)

#### Project Issue Information

**Issue Name :** Return Damper Missing in ROOM MOO 142  
**Description :** Return Grille R1N-26 is missing the damper to TAB.  
**Created By :** National TAB                      **Assigned To :** National TAB - Antonio Flores-De La Cruz  
**Status :** Open  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 03/03/2026 - Antonio Flores-De La Cruz - National TAB

#### Project Issue File Details



03/03/2026



03/03/2026