

Issue List

- VAV AT-E102 Missing Diffuser
- VAV AT-E103 Wrong Location
- VAV AT-E117 Missing Grille
- VAV AT-N116 Missing Diffuser
- VAV AT-N141 Missing Diffuser




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : VAV AT-E102 Missing Diffuser
Description : Diffuser E102-1 is missing in room STORAGE 108A
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Asset Tag :**
Originated Date : 01/21/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



01/21/2026



01/21/2026



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : VAV AT-E103 Wrong Location
Description : VAV AT-E103 is installed in the wrong location per the drawings. It should have been installed in MXG/ADM E103 but instead was installed in room OPEN OFFICE E102. A diffuser is installed in room E103, but it is connected to VAV AT-E101, which is incorrect.


Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz

Status : Open

Priority : **Urgent** **Asset Tag :**

Originated Date : 01/21/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



01/21/2026



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : VAV AT-E117 Missing Grille
Description : Diffuser E117-1 in CORRIDOR E115 is missing. Upon inspection, it appears that the duct is attached to the VAV but it stops at the brick wall of room BREAK E117 and doesn't penetrate to the other side.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Asset Tag :**
Originated Date : 01/21/2026 - Antonio Flores-De La Cruz - National TAB


Project Issue File Details



01/21/2026



01/21/2026



01/21/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : VAV AT-N116 Missing Diffuser
Description : Diffuser missing in Passage N115 (N116-1).
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 11/11/2025 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



11/11/2025




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : VAV AT-N141 Missing Diffuser
Description : Diffuser in Corridor N140 (N141-1) is missing.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 11/11/2025 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



11/11/2025

Project Issue Response Details

- **01/21/2026 National TAB - Antonio Flores-De La Cruz**
 - SAW MECHANICAL CONTRACTOR FIXING ISSUE, WILL CHECK
- **11/12/2025 National TAB - Antonio Flores-De La Cruz**
 - Diffuser was installed, but after attempting to balance, the supply grille in Shirt Office N143 (N141-2) is swapped with the grille for the return. It must be swapped.

