

Issue List

- EF-14 Not Operational
- EF-15 Not Operational
- EF-22 Missing Dampers
- EF-23 High Flow
- EF-23 Missing Grille
- EF-26 Low Flow
- EF-3 Not operational and Motor Damper not wired
- EF-4 High Flow
- EF-4 Noise at Fan
- Hanger EFs Not Operational
- Incorrect Connected Return Grille
- Incorrectly Installed Duct for Return
- Missing Damper for Return Grille
- Missing Damper for Return Grille in E107
- Missing Multiple Return Dampers in ROOM READY/BREAKROOM N151
- Missing Return Damper for CORRIDOR N153
- Missing Return Damper in OPEN OFFICE E123
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153A
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153C
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153E
- Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153F
- Missing Return Damper in ROOM AVIONICS ELEMENT CHIEF N116
- Missing Return Damper in ROOM AXMS CHIEF N153B
- Missing Return Damper in ROOM CLASSROOM E108

- Missing Return Damper in ROOM CMF CHIEF N117
- Missing Return Damper in ROOM COMMANDER N141
- Missing Return Damper in ROOM COMSEC N110AA
- Missing Return Damper in ROOM CONFERENCE N118
- Missing Return Damper in ROOM CTK N131
- Missing Return Damper in ROOM ENG ELEMENT CHIEF N113A
- Missing Return Damper in Room PRO SUP N144
- Missing Return Damper in ROOM SHIRT OFFICE N143
- Missing Return Damper in ROOM SIPR N110A
- Missing Return Dampers in Offices
- Missing Return Dampers in ROOM AVIONICS N110
- MUA-2 Dirty Filters
- Multiple Dampers Missing HANGER SHOP NORTH
- Multiple Return Dampers missing
- Return Damper Missing in ROOM MOO 142



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-14 Not Operational
Description : EF-14 is not operational because the motor sheave and belt are damaged. The motor sheave broke into two pieces.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-15 Not Operational

Description : EF-15 shaft to the blower is not connected at this time.

Created By : National TAB

Assigned To : National TAB - Antonio Flores-De La Cruz


Status : Open

Priority : Urgent

Asset Tag :

Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-22 Missing Dampers
Description : EF-22 is missing all dampers but 3 to TAB. The grilles with dampers are: EF22-1, EF22-3, and EF22-4. Recommended to install dampers with access due to the hard ceiling.
Created By : National TAB
Assigned To : National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent
Asset Tag :
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-23 High Flow
Description : EF-23 is 37% above design (407 CFM ACTUAL / 300 CFM DESIGN) and requires a sheave change to reduce flow. Motor sheave is on the lowest setting. Unable to balance due to a diffuser missing as well.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB




NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : EF-23 Missing Grille
Description : Grille EF-23-1 in JANITORS E118 is not installed.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : High **Asset Tag :**
Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026



02/12/2026



02/12/2026



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-26 Low Flow
Description : EF-26 is at 66% of design (99 CFM ACTUAL / 150 CFM DESIGN). The speed dial is at max. A possible cause could be a partially opened exhaust motorized damper. It was found that there is a damper at the takeoff and one at the arm of the equipment where the duct connects, which may add resistance to the system.

Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz

Status : Open

Priority : Urgent **Asset Tag :**

Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-3 Not operational and Motor Damper not wired
Description : The exhaust damper for EF-3 is not wired, and Controls stated that the fan is not wired to be operational.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



02/12/2026

Project Issue Response Details

- **03/05/2026 National TAB - Antonio Flores-De La Cruz**
 - FAN APPEARS WIRED, BUT DAMPER IS STILL NOT WIRED TO OPEN.



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-4 High Flow
Description : EF-4 is 18% above design (706 CFM ACTUAL / 600 CFM DESIGN) and requires a sheave change to reduce flow. Motor sheave is on the lowest setting. Grilles are balanced proportionally high.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : High **Asset Tag :**
Originated Date : 02/10/2026 - Antonio Flores-De La Cruz - National TAB



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : EF-4 Noise at Fan
Description : One of the fan blades is grinding against the housing of the fan.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : [Medium](#) **Asset Tag :**
Originated Date : 02/10/2026 - Antonio Flores-De La Cruz - National TAB



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Hanger EFs Not Operational
Description : EF-9 through EF-19, EXCEPT EF-13, are not operational. Controls stated the exhaust fans might be wired incorrectly. Further investigation is required.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue Response Details

- **03/05/2026 National TAB - Antonio Flores-De La Cruz**
 - MECHANICAL STATED ALL BUT EF-9, EF-14, AND EF-15 ARE OPERATIONAL NOW. WILL CHECK AND TAB





NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Incorrect Connected Return Grille
Description : Return Grille R1N-34 is connected to the supply, not the return.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details






NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Incorrectly Installed Duct for Return
Description : Grilles R1N-28 and R1N-29 were attached to EF-22 ductwork.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026



NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Damper for Return Grille
Description : Return Grille R2E-7 in E107A is missing the damper to balance.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/02/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/02/2026



03/02/2026



NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Damper for Return Grille in E107
Description : Grille R2E-8 is missing the damper to balance.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/02/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/02/2026



03/02/2026



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Multiple Return Dampers in ROOM READY/BREAKROOM N151
Description : Return grilles: R1N-15, R1N-16, R1N-23, and R1N-24 are all missing dampers to TAB.


Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz

Status : Open

Priority : **Urgent** **Asset Tag :**

Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper for CORRIDOR N153
Description : Grille R1N-21 is missing the damper ot TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details






NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in OPEN OFFICE E123
Description : Damper for Grille R2E-15 is missing to balance.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/02/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/02/2026



03/02/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153A
Description : Grille R1N-22 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153C
Description : Grille R1N-19 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026



NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153E
Description : Grille in ROOM AMXS FLIGHT CHIEF N153E is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026



NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM AMXS FLIGHT CHIEF N153F
Description : Grille R1N-18 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM AVIONICS ELEMENT CHIEF N116
Description : Grille R1N-8 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM AXMS CHIEF N153B
Description : Grille R1N-20 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM CLASSROOM E108
Description : Damper for Grille R2E-14 in ROOM CLASSROOM E108 is missing to balance.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/02/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details






NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM CMF CHIEF N117
Description : Grille R1N-9 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details







NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM COMMANDER N141
Description : Grille R1N-17 is missing the return damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM COMSEC N110AA
Description : Grille R1N-5 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM CONFERENCE N118
Description : Grille R1N-10 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM CTK N131
Description : Grille R1N-30 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Damper in ROOM ENG ELEMENT CHIEF N113A
Description : Grille R1N-12 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in Room PRO SUP N144
Description : Return Damper for Grille R1N-45 is missing to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026



NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM SHIRT OFFICE N143
Description : Grille R1N-14 is missing the return damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Damper in ROOM SIPR N110A
Description : Grille R1N-4 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Missing Return Dampers in Offices
Description : Grilles R2E-12 and R2E-13 are missing their dampers to balance the return.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/02/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details





NCANG Repair Bldg 51 (Charlotte, NC)


Project Issue Information

Issue Name : Missing Return Dampers in ROOM AVIONICS N110
Description : Grilles R1N-6 and R1N-7 are missing the dampers to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026



NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : MUA-2 Dirty Filters

Description : MUA-2 filters are dirty and must be changed to TAB.

Created By : National TAB

Assigned To : National TAB - Antonio Flores-De La Cruz

Status : Open

Priority : Urgent

Asset Tag :

Originated Date : 02/12/2026 - Antonio Flores-De La Cruz - National TAB




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Multiple Dampers Missing HANGER SHOP NORTH
Description : Return Grilles R1N-31 through R1N-37, EXCEPT R1N-34, are missing dampers to balance the return.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026



03/03/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Multiple Return Dampers missing
Description : Dampers for Return Grilles: RE2-1 through RE2-5 are missing to balance.
Created By : National TAB
Assigned To : National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent
Asset Tag :
Originated Date : 03/02/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/02/2026



03/02/2026




NCANG Repair Bldg 51 (Charlotte, NC)

Project Issue Information

Issue Name : Return Damper Missing in ROOM MOO 142
Description : Return Grille R1N-26 is missing the damper to TAB.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : **Urgent** **Asset Tag :**
Originated Date : 03/03/2026 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



03/03/2026



03/03/2026