

Issue List

- DOAS - 1 Temperature Sensor Malfunctioning
- EF-DISH Leakage
- MUA-1 Does not operate normally
- MUA-1 Gas Test
- RTU-1 Temperature Sensor



09-22-25 Firebirds Chesterfield, VA

Project Issue Information

Issue Name : DOAS - 1 Temperature Sensor Malfunctioning
Description : DOAS - 1 temperature sensor not reading properly. It causes the unit to shutdown on an overheat fault.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 09/24/2025 - Alex Bauer - National TAB

Project Issue File Details



09/24/2025



09-22-25 Firebirds Chesterfield, VA

Project Issue Information

Issue Name : EF-DISH Leakage
Description : Dishwasher ductwork needs duct sealant at certain joints near the bends. Also, possible leakage at the curb. Rope Gasket is helping but may not be enough due to open corners at the curb.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 09/25/2025 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



09/25/2025



09/25/2025



09/25/2025



09-22-25 Firebirds Chesterfield, VA

Project Issue Information

Issue Name : MUA-1 Does not operate normally
Description : MUA-1 does not turn on when turning on fans with the HMI on the hood. For the purposes of TAB, it was put into test mode. Recommended to review wiring and ensure proper operation.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 09/25/2025 - Antonio Flores-De La Cruz - National TAB



09-22-25 Firebirds Chesterfield, VA

Project Issue Information

Issue Name : MUA-1 Gas Test

Description : Permanent gas not installed yet, unable to test out the heater.

Created By : National TAB

Assigned To : National TAB - Antonio Flores-De La Cruz

Status : Open

Priority : [Medium](#)

Asset Tag :

Originated Date : 09/25/2025 - Antonio Flores-De La Cruz - National TAB



09-22-25 Firebirds Chesterfield, VA


Project Issue Information

Issue Name : RTU-1 Temperature Sensor
Description : Sensor near beverage zone is not communicating properly with RTU-1.
Created By : National TAB **Assigned To :** National TAB - Antonio Flores-De La Cruz
Status : Open
Priority : High **Asset Tag :**
Originated Date : 09/24/2025 - Antonio Flores-De La Cruz - National TAB

Project Issue File Details



09/24/2025



09/24/2025

