

## Issue List

- EF-1 Conduit Box Cover Missing
- EF-2 Back Draft Damper Obstruction



**10-02-23 ARBY'S 2010 - PURCELL, OK**

**Project Issue Information**

**Issue Name :** EF-1 Conduit Box Cover Missing  
**Description :** EF-1 for Hood missing electrical conduit box cover. Leaving wiring exposed to climate conditions.  
**Created By :** National TAB                      **Assigned To :** National TAB - Wale Odofin  
**Status :** Open  
**Originated Date :** 10/03/2023 - Darius Payne - National TAB

Project Issue File Details



C2C47CF5\_365D\_4534\_B9..  
10/03/2023



41F78B92\_8652\_48E4\_81..  
10/03/2023



**10-02-23 ARBY'S 2010 - PURCELL, OK**

**Project Issue Information**

**Issue Name :** EF-2 Back Draft Damper Obstruction  
**Description :** EF-2 airflow is 174 CFM out of 300 CFM due to back draft damper not being able to fully open and hitting bottom of the fan. Recommend moving the damper lower in the duct.  
**Created By :** National TAB                      **Assigned To :** National TAB - Brianna Biggs  
**Status :** Open  
**Originated Date :** 10/03/2023 - Darius Payne - National TAB

Project Issue File Details

- 1. [Open](#) IMG\_1611.mp4  
10/03/2023



0F4F53D5\_60EC\_4E10\_B3..  
10/03/2023