

**Report By:**

National TAB  
1329 E. KEMPER ROAD  
SUITE 4210  
CINCINNATI, OH 45246



**Report: ISSUES**

**Function: Test, Adjust, & Balance**

**Date: 08/27/2025**

**Completed By: National TAB**

# **PROJECT**

**08-25-25 CHIPOTLE #5270 LOUISVILLE, KY  
(PRESTON CENTER)**

10415 PRESTON HWY

LOUISVILLE, KY 40229

## **Client**

Chipotle Mexican Grill  
610 Newport Center Drive, Suite 1100

Newport Beach, CA 92660

# National TAB

Project: 08-25-25 CHIPOTLE #5270 LOUISVILLE, KY (PRESTON CENTER)

## Table Of Contents

| Section | Page # |
|---------|--------|
| ISSUES  | 3      |

## Issue List

- HOOD NON-FUNCTIONAL
- Missing Diffusers
- Missing O.B. Dampers
- MUA ORIENTATION
- RESTROOM BACK DRAFT DAMPER



**08-25-25 CHIPOTLE #5270 LOUISVILLE, KY (PRESTON CENTER)**

**Project Issue Information**

**Issue Name :** HOOD NON-FUNCTIONAL  
**Description :** Manufacturing malfunction causing the hood not to function. Internal solenoid integral to the hood is bad and preventing the HMI and startup of the hood.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Closed  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 08/27/2025 - Cavin Van - National TAB

Project Issue File Details



08/27/2025



**08-25-25 CHIPOTLE #5270 LOUISVILLE, KY (PRESTON CENTER)**

**Project Issue Information**

**Issue Name :** Missing Diffusers  
**Description :** Diffusers 2-1 and 2-2 are missing and Diffusers 2-6 and 2-7 need O.B. Dampers.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Closed  
**Priority :** **Urgent**                                      **Asset Tag :**  
**Originated Date :** 08/27/2025 - Cavin Van - National TAB

Project Issue File Details



08/27/2025



08/27/2025



**08-25-25 CHIPOTLE #5270 LOUISVILLE, KY (PRESTON CENTER)**

**Project Issue Information**

**Issue Name :** Missing O.B. Dampers  
**Description :** All kitchen diffusers are missing O.B. Dampers.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Closed  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 08/27/2025 - Cavin Van - National TAB

Project Issue File Details



08/27/2025



**08-25-25 CHIPOTLE #5270 LOUISVILLE, KY (PRESTON CENTER)**

**Project Issue Information**

**Issue Name :** MUA ORIENTATION  
**Description :** MUA orientation shows the outside air intake is close to the exhaust fan.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Closed  
**Priority :** Urgent                                      **Asset Tag :**  
**Originated Date :** 08/28/2025 - Cavin Van - National TAB



**08-25-25 CHIPOTLE #5270 LOUISVILLE, KY (PRESTON CENTER)**


**Project Issue Information**

**Issue Name :** RESTROOM BACK DRAFT DAMPER  
**Description :** Restroom back draft damper is too close to the fan causing it to only open up 65%. Recommend lowering backdraft damper.  
**Created By :** National TAB                      **Assigned To :** National TAB - Dan Hertenstein  
**Status :** Open  
**Priority :** High                                      **Asset Tag :**  
**Originated Date :** 08/27/2025 - Cavin Van - National TAB

Project Issue File Details



08/27/2025



08/27/2025