

# Sierra Grill

## CheckList Information

**Name :** Sierra Grill Exhaust pressurized water test      **Status :** NotSubmitted  
**Assigned Organization :** All State Fire Midwest      **Asset :**  
**Requesting Organization :** All State Fire Midwest

## CheckList Item Details

Pressurized Water Test section 1 duct work - Main      Fail  
Cook Line. Exhaust duct meets NFPA 17a and 96  
standard.



IMG\_7407\_1\_.jpg



IMG\_7408\_1\_.jpg



IMG\_7409.jpg

Pressurized Water Test Section 2 duct work - Main      Fail  
Cook Line. Exhaust duct meets NFPA 17a and 96  
standard



IMG\_7410.jpg



IMG\_7411.jpg




IMG\_7412.jpg


Pressurized Water Test Section 3 ductwork - Main      Fail  
Cook Line. Exhaust duct meets NFPA 17a and 96  
standard.



IMG\_7414\_1\_.jpg



IMG\_7415\_1\_.jpg



IMG\_7416\_1\_.jpg

Pressurized Water Test Section 4 ductwork - Main Cook Line. Exhaust duct meets NFPA 17a and 96 standard. Fail



IMG\_7417\_1\_.jpg



IMG\_7418\_1\_.jpg



IMG\_7419\_1\_.jpg

Pressurized Water Test Section 5 ductwork - Main Cook Line. Exhaust duct meets NFPA 17a and 96 standard. Fail



IMG\_7422\_1\_.jpg



IMG\_7423\_1\_.jpg

Method-process for pressure testing. 1600 psi pressurize water jet utilizing photo-lumencent amplifier and UV Light test at all joints in the main cook line.

- [Open](#) Processpressuretest2.MOV



**Processpressuretest1.jpg**

Pressurized Water Test - Main Cook line - Misc Photos Fail

- [Open](#) Prepressuretestconditions.MOV


Pressurized Water Test - Main Cook line- Misc Photos Fail



**Leaktestipad1main.jpeg**




**Leaktestipad2main.jpeg**



**Leaktestipad3main.jpeg**

Pressurized Water Test - Main Cook Line Misc Video Fail



**Leaktestmain.jpeg**

---

Wood fire charbroiler duct work tested?

No

---

Main Cook line pant-leg duct tested?

Yes

**Notes/Comments :**