



Sierra Grill

CheckList Information

Name : Sierra Grill Exhaust pressurized water test **Status :** NotSubmitted
Assigned Organization : All State Fire Midwest **Asset :**
Requesting Organization : All State Fire Midwest

CheckList Item Details

Pressurized Water Test section 1 duct work - Main Fail
Cook Line. Exhaust duct meets NFPA 17a and 96 standard.



IMG_7407_1_.jpg



IMG_7408_1_.jpg



IMG_7409.jpg

Pressurized Water Test Section 2 duct work - Main Fail
Cook Line. Exhaust duct meets NFPA 17a and 96 standard



IMG_7410.jpg



IMG_7411.jpg




IMG_7412.jpg


Pressurized Water Test Section 3 ductwork - Main Cook Line. Exhaust duct meets NFPA 17a and 96 standard. Fail



IMG_7414_1_.jpg



IMG_7415_1_.jpg



IMG_7416_1_.jpg

Pressurized Water Test Section 4 ductwork - Main Cook Line. Exhaust duct meets NFPA 17a and 96 standard. Fail



IMG_7417_1_.jpg



IMG_7418_1_.jpg



IMG_7419_1_.jpg

Pressurized Water Test Section 5 ductwork - Main Cook Line. Exhaust duct meets NFPA 17a and 96 standard.

Fail



IMG_7422_1_.jpg



IMG_7423_1_.jpg

Method-process for pressure testing. 1600 psi pressurize water jet utilizing photo-lumencent amplifier and UV Light test at all joints in the main cook line.

- [Open](#) Processpressuretest2.MOV



Processpressuretest1.jpg

Pressurized Water Test - Main Cook line - Misc Photos

Fail

- [Open](#) Prepressuretestconditions.MOV

Pressurized Water Test - Main Cook line- Misc Photos


Fail



Leaktestipad1main.jpeg




Leaktestipad2main.jpeg



Leaktestipad3main.jpeg

Pressurized Water Test - Main Cook Line Misc Fail
Video



Leaktestmain.jpeg

Wood fire charbroiler duct work tested? No

Main Cook line pant-leg duct tested? Yes

Notes/Comments :