

TAB Punch List - Mar 25, 2024

Prepared by Michael McDonnell

Mar 25, 2024

Description

2 tasks in this report.

Contents

#593 Grease Cleanout Doors Sized Incorrectly.....	2
#563 RTU SENSOR LABELS: Improper Label.....	4

L05068_Spring Station FSU (KY)

962 Breckenridge Lane, Louisville, Kentucky

L1020005068

#593 Grease Cleanout Doors Sized Incorrectly.

Status

Open

Type

Planned Work

List

TAB Punch List

Description

Cleanout doors do not meet size specifications listed in cleanout door schedule on M-250.

Assignees

doug@thorndaleconstruction.com

Watchers

doug@thorndaleconstruction.com

Created


Mar 20, 2024 1:27 PM
mmcdonnell@nationaltab.com

Last Updated

Mar 20, 2024 1:31 PM

Sheet

M-250



Photos

L05068_Spring Station FSU (KY)

962 Breckenridge Lane, Louisville, Kentucky

L1020005068



IMG_2813

Michael McDonnell

Mar 20, 2024 1:30 PM



IMG_2826

Michael McDonnell

Mar 20, 2024 1:30 PM



IMG_2814

Michael McDonnell

Mar 20, 2024 1:30 PM

#563 RTU SENSOR LABELS: Improper Label

Status

Open

Type

Issue

Location

Site

List

TAB Punch List

Description

See M-501, Detail 1, Note 4:
1/4" High white
Lettering on black
background. Label on wall
ADJACENT TO DEVICE.
Sensors improperly
Labeled.

Photos

Assignees

doug@thorndaleconstruction.com

Watchers

doug@thorndaleconstruction.com

Created


Mar 18, 2024 2:05 PM
mmcdonnell@nationaltab.com

Last Updated

Mar 18, 2024 3:45 PM

Sheet

M-501



L05068_Spring Station FSU (KY)

962 Breckenridge Lane, Louisville, Kentucky

L1020005068



20240318_161157_photo

Michael McDonnell

Mar 18, 2024 3:12 PM