Issue List

- EF Backdraft Damper
- EF-3 Missing Speed Controller
- RTU-2 Dirty Filters

01-12-26 WAWA #6618 RICHMOND, VA

Project Issue Information

Issue Name : EF Backdraft Damper

Description : EF-1 and EF-2 both do not have a backdraft damper installed.

Created By :	National TAB	**Assigned To :**	National TAB - Brianna Biggs
Status :	Open		
Priority :	Low	**Asset Tag :**	
Originated Date :	01/14/2026 - John Barresi - National TAB		

01-12-26 WAWA #6618 RICHMOND, VA

Project Issue Information

Issue Name :	EF-3 Missing Speed Controller		
Description :	Exhaust fan doesn't have a variable speed controller installed. Fan currently exhausting 240CFM out of 200CFM design. (120%)		
Created By :	National TAB	**Assigned To :**	National TAB - Will Turnbough
Status :	Open		
Priority :	Urgent	**Asset Tag :**	
Originated Date :	01/20/2026 - John Barresi - National TAB		

01-12-26 WAWA #6618 RICHMOND, VA

Project Issue Information

Issue Name : RTU-2 Dirty Filters

Description : Unit's final filters are dirty. Recommend replacing with clean MERV filters.

Created By : National TAB

Assigned To : National TAB - Brianna Biggs

Status : Open

Priority : Medium

Asset Tag :

Originated Date : 01/20/2026 - John Barresi - National TAB