NATIONAL TAB INTELLIGENCE

Comfort. Under Control.
www.nationaltab.com

10-07-24 FREDDY'S HCI - COUNCIL BLUFFS, IA (1305) - RENEW

Project Issue Information

Issue Name : Rtu1 for kitchen inducer motor

Description : Rtu1 upon arrival heat would not come on because inducer motor has broke a bit and is hanging a little and not allowing it to spin properly. I pushed it in a bit and got it to start. Whole time I was here after doing so it would come on and work with a call for heat. Alerted manager about issue to get it fixed before it gets too cold.

Created By : National TAB

Assigned To : National TAB - Kyle Henry

Status : Open

Priority : Urgent

Asset Tag :

Originated Date : 10/10/2024 - Kyle Henry - National TAB

Project Issue File Details



10/10/2024

10/10/2024