Comfort. Under control.

10-03 HAWAIIAN BROS - O'FALLON, MO

Project Issue Information

Issue Name : RTU3 OA damper does not function

Description : OA damper does not function. Spoke with Adam from CAS, he will be out tomorrow to install the new OA module. This was an existing issue found during startup.

Created By : National TAB

Assigned To : National TAB - Will Turnbough

Status : Open

Originated Date : 10/03/2022 - Travis Halter - National TAB