02-17-25 FREDDY'S - SAPPINGTON (ST LOUIS, MO) - RENEW

Project Issue Information

Issue Name : RTU-2 blower fan

Description : Blower fan making a lot of noise while operating. Recommend service to inspect alignment on fan for possible cause of noise.

Created By : National TAB

Assigned To : National TAB - Dylan Crisman

Status : Open

Priority : High

Asset Tag :

Originated Date : 02/26/2025 - Dylan Crisman - National TAB

Project Issue File Details

1. Open IMG_7139.mp4