12-09-24 SHAKE SHACK #1523 PITTSBURGH, PA (ANDREW DRIVE) TAB, IAQ, CX

Project Issue Information

Issue Name :	Condenser for MUA-1 not operational		
Description :	Condenser for MUA-1 is not operational, cooling test mode shows it's in cooling but condenser never kicks on for cooling. Also tried hitting contactors, no change in operation. No voltage recorded at Condenser. Recommend mechanical/electrician diagnose for correction.		
Created By :	National TAB	**Assigned To :**	National TAB - Dylan Crisman
Status :	Open		
Priority :	Urgent	**Asset Tag :**	
Originated Date :	12/10/2024 - Dylan Crisman - National TAB		