Comfort. Under control.

07-11 CULVERS - ELLISVILLE, MO

Project Issue Information

Issue Name : Diffuser note RTU1 SGRD 1-12 low on flow

Description : Branch is low on flow due to hard right angle coming out of one of the main duct lines. Diffuser is in an open space and should not create comfort issues

Created By : National TAB **Assigned To :** National TAB - Will Turnbough

Status : Pending

Originated Date : 07/13/2022 - Jacob Davidson - National TAB

Project Issue File Details

Aboveceiling.jpeg

Belowceiling.jpeg