



Comfort. Under control.

**05-09 Shake Shack #1352 (Chesterfield, MO) COMMISSIONING**

**Project Issue Information**

**Issue Name :** GFI not resetting  
**Description :** GFI not resetting: FRYER line interior wall GFI not resetting after trip test. Repair and validate ALL cookline GFI's will reset properly  
**Created By :** National TAB **Assigned To :** Akron Electric - Patrick Clancy  
**Status :** Open  
**Originated Date :** 05/23/2022 - Dan Hertenstein - National TAB

Project Issue File Details



**GFIoutlet.jpeg**



**Frylinelocation.jpeg**

Project Issue Response Details

- 06/06/2022 National TAB - Travis Halter
  - GFI still does not reset, tested power as well in case. No power detected.