

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: HVAC TAB FINDINGS
Function: Test, Adjust, & Balance
Date: 10/14/2024
Completed By: National TAB

PROJECT
Shindig Restaurant (Indianapolis, IN)

1351 Roosevelt Avenue

Indianapolis, IN 46202

Client

CAPTIVE-AIRE R120
1329 E. Kemper Road
Suite 4210
Cincinnati, OH 45246

National TAB

Project: Shindig Restaurant (Indianapolis, IN)

Table Of Contents

Section	Page #
Issue Data	3

Issue List

- Rtu 1 diffusers
- Rtu 1 Filters
- Rtu 3 filters
- Rtu 5 not running
- Rtu 7 economizer
- RTU5 missing diffuser
- Vestibule supply



Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : Rtu 1 diffusers
Description : Diffuser layout for Rtu 1 doesn't match design. Design calls for 4 diffusers by front of building, 3 are installed.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Project Issue File Details



10/14/2024



Comfort. Under Control.
www.nationaltab.com

Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : Rtu 1 Filters
Description : Filters in Rtu 1 are dirty and will need to be replaced for TAB.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : Rtu 3 filters
Description : Incorrect filters installed in rtu3. Instead of installing 4-20"x20"x2" filters, 8-20"x20"x1" filters were installed. This will need to be addressed for TAB.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Project Issue File Details



10/14/2024



Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : Rtu 5 not running
Description : Rtu 5 is switched off at the disconnect because it had some sort of issue.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : Rtu 7 economizer
Description : Economizer for rtu7 not wired properly. Unable to set and adjust outdoor air intake.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Project Issue File Details



10/14/2024

Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : RTU5 missing diffuser
Description : Rtu 5 is missing diffuser 3. Unable to balance system properly until install.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Project Issue File Details





Shindig Restaurant (Indianapolis, IN)

Project Issue Information

Issue Name : Vestibule supply
Description : Rtu 4 is designed to supply the vestibule. However, the ductwork has not been ran to the vestibule.
Created By : National TAB **Assigned To :** National TAB - Joe Hertenstein
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 10/14/2024 - Gabe Merk - National TAB

Project Issue File Details



10/14/2024