



Comfort. Under control.

## 11-07 FAMILY DOLLAR - SARDIS, AR

### Project Issue Information

**Issue Name :** RTU1 Motor not running

**Description :** After balance was completed the next morning when installing duct plugs it was found that the motor was not rotating. Found that the pulleys rotate freely, voltage to the unit is correct and all wires have amps up to the motor. Motor is bad and will need to be replaced.

**Created By :** National TAB

**Assigned To :** National TAB - Travis Halter

**Status :** Open

**Originated Date :** 11/10/2022 - Travis Halter - National TAB

#### Project Issue Response Details

- **11/10/2022**      **National TAB - Travis Halter**
  - Disconnect was left off.