

Report By:

National TAB
1329 E. KEMPER ROAD
SUITE 4210
CINCINNATI, OH 45246



Report: Punchlist
Function: Test, Adjust, & Balance
Date: 03/03/2025
Completed By: National TAB

PROJECT
03-03-25 FIREBIRDS LIBERTY TOWNSHIP,
OH

7685 BLAKE ST

LIBERTY TOWNSHIP, OH 45069

Client

FIREBIRD RESTAURANTS
8700 Red Oak Blvd, Unit J

CHARLOTTE, NC 28217

National TAB

Project: 03-03-25 FIREBIRDS LIBERTY TOWNSHIP, OH

Table Of Contents

Section	Page #
Issues	3

Issue List

- Diffuser 1-10
- Ef-3 CURB LEAKAGE
- EF-3 Unable to use hinge kit.



03-03-25 FIREBIRDS LIBERTY TOWNSHIP, OH

Project Issue Information

Issue Name : Diffuser 1-10
Description : Diffuser 1-10 flex has come loose from diffuser. Airflow will not meet design until rectified.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Medium **Asset Tag :**
Originated Date : 04/23/2025 - Gabe Merk - National TAB

Project Issue File Details



04/23/2025



04/23/2025



03-03-25 FIREBIRDS LIBERTY TOWNSHIP, OH

Project Issue Information

Issue Name : Ef-3 CURB LEAKAGE
Description : Unable to balance ef-3 due to excessive curb leakage.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Urgent **Asset Tag :**
Originated Date : 04/23/2025 - Gabe Merk - National TAB

Project Issue File Details



04/23/2025



03-03-25 FIREBIRDS LIBERTY TOWNSHIP, OH

Project Issue Information

Issue Name : EF-3 Unable to use hinge kit.
Description : EF-3 Unable to use hinge kit due to installation location of supplied power.
Created By : National TAB **Assigned To :** National TAB - Will Turnbough
Status : Open
Priority : Medium **Asset Tag :** KEF3
Originated Date : 03/03/2025 - Cody Collett - National TAB